

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Douglas Ong Chu Chong

Date: 22 Nov 2021

Preliminary Advice

| | | | |
|--------------------|------------------------|-------------------------|--------------|
| Insured Vehicle No | : GBL4508P | Accident Date | : 12/11/2021 |
| TP Vehicle No | : SJA4419B | Assignment Date | : 16/11/2021 |
| Make | : TOYOTA COROLLA | Est. Duration of Repair | : |
| Date of Inspection | : 16/11/21 | | |
| Inspection At | : CHENG HOE MOTOR PL 6 | | |

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 4,912.50 |
| Revised Amount | :S\$ | 3,968.15 |
| Check Items (Estimated) | :S\$ | 668.68 |
| Total | :S\$ | 4,636.83 |
| Lump Sum Repair | :S\$ | |

Total Loss Consideration

| | |
|--------------------|------|
| New for Old Value | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate | :S\$ |
| Salvage Value | :S\$ |
| Margin for Repair | :S\$ |

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- () Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis.

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost.