

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21011616/KVF3E2

Date: 07/12/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001875073

Claimant Vehicle No : SJA4419B

Insured Vehicle No : GBL4508P

Date of Loss: 12/11/2021

Nature of Claim: TP Claim No: 265426

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJA4419B**

Make & Model: TOYOTA COROLLA, 1.5 X AXIO (A)

Engine No: 1NZC780784

Reg. Date: 10/12/2007 (Man. Year: 2007)

Chassis No: NZE1416054660

Colour: Metallic Silver

Odometer: 261047 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Michelin 7 mm

Rear Left Side: Michelin 7 mm

Front Right Side: Michelin 7 mm

Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,202.50	2,536.88	665.62	20.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,710.00	1,560.00	150.00	8.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,912.50	4,096.88	815.62	16.60
Approved Total (Overridden) (S\$)		3,200.00		
(S\$)	4,912.50	3,200.00	1,712.50	34.86
+ GST 7.00/7.00% (S\$)	343.88	224.00	119.88	34.86
Nett Amount (S\$)	5,256.38	3,424.00	1,832.38	34.86

INSPECTION

Date of Assignment: 16/11/2021

Date Inspected: 16/11/2021 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)

Blk 1019 #01-374/382, Yishun Industrial Park A
Singapore 768761

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Nov 2021)
Parts:	143	TOYOTA COROLLA 1.5 X AXIO (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJA4419B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	565.20 FL	*565.20 FL
2	1		*REAR BUMPER LH BRACKET	Bent	59.80 FL	*59.80 FL
3	1		*REAR BUMPER LH SIDE RETAINER	Distorted	81.76 FL	*81.76 FL
4	6		*REAR BUMPER CLIPS	Necessary	21.00 FL	*21.00 FL
5	1		*REAR BOOT	Bent	817.53 FL	*817.53 FL
6	1		*REAR BOOT INNER LOCK	Distorted	111.83 FL	*111.83 FL
7	1		*REAR BOOT INNER RUBBER (\$167.20) (50%)	Cut	125.40 FS	*83.60 FS
8	1		*REAR BOOT EMBLEM (AXIO)	Necessary	45.10 FL	*45.10 FL
9	1		*REAR BOOT EMBLEM	Necessary	40.10 FL	*40.10 FL
10	1		*REAR BOOT OUTER GARNISH WITH LOGO	Cracked	216.50 FL	*216.50 FL
11	1		*REAR CENTRE PANEL	Bent	514.20 FL	*514.20 FL
12	1		*REAR CENTRE PANEL INNER TOP GARNISH	Mtg Distorted	166.25 FL	*166.25 FL
13	1		*TAILLAMPS	O/S Cracked / N/S Serviceable	730.20 FL	*365.10 FL
14	1		*SET REVERSE SENSOR	Dented	200.00 FS	*200.00 FS
15	1		*REVERSE CAMERA	Serviceable	350.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,044.87	3,287.97
- List Item Discount on L Items 25.00/25.00% (\$\$)	842.37	751.09
Total Parts (\$\$)	3,202.50	2,536.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, REAR BOOT & ATTACHMENT, CUT, WELD & RENEW REAR PANEL, KNOCK & REPAIR REAR COMPARTMENT & REALIGN THE SAME	New	800.00	700.00
2	PUTTY & RESPRAY ON REAR PANEL, BOOT, REAR BUMPER, HINGES, COMPARTMENT & REAR AFFECTED AREAS	New	850.00	800.00
3	RUSTPROOFING	New	60.00	60.00
Gross Labour Cost (\$\$)			1,710.00	1,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >