



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMY 51S

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|---|--|---------------|---------------------------|-------------------|
| | <u>REPLACEMENT OF PARTS</u> | | | |
| 1 | FRONT BUMPER | CUT | 1,651.00 | 1,651.00 |
| 1 | FRONT BUMPER SENSOR LH | CUT | 185.00 | 185.00 |
| 1 | FRONT FENDER LH | DENTED | 966.00 | 915.25 |
| 1 | FRONT HEADLAMP LH | CRACKED | 3,411.00 | 3,059.00 |
| | LESS 10% DISCOUNT | | - | -581.03 |
| | | | 6,213.00 | 5,229.22 |
| | <u>LABOUR</u> | | | |
| | LABOUR CHARGE FOR REMOVE DAMAGED PORTION, STRAIGHTEN, PANEL BEAT AND RENEW REPLACED PARTS. | | 700.00 | 600.00 |
| | TO PUTTY AND SPRAY PAINTING TO THE REPLACED / REPAIRED PARTS. | | 700.00 | 400.00 |
| | TO APPLY RUSTPROOF TREATMENT TO THE REPLACED / REPAIRED PARTS. | NOT NECESSARY | 200.00 | - |
| | TO CHECK AND FOCUS THE HEADLAMP. | NOT NECESSARY | 80.00 | - |
| | | | 1,680.00 | 1,000.00 |
| GRAND TOTAL | | | 7,893.00 | 6,229.22 |
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | | 4,950.00 |

Report Ref No. CS/LPC21011618/Buf3e2

LIM TEOW GUAN

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.