11/29/21, 2:59 PM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EQI21011619/R1VF3E2

**Date:** 29/11/2021

**REFERENCE** 

Handling Insurer: EQ Insurance Company Ltd Policy No: DMCPHQ21-001542

Claimant Vehicle SHC8609G Insured Vehicle No: GBF9382H

No:

Date of Loss: 13/11/2021 Nature of Claim: TP Claim No: DM21HO01699

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SHC8609G

Make & Model: HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A) Engine No: G4LEKU421513

Reg. Date: 25/02/2021 (Man. Year: 2019) Chassis No: KMHC851CVLU192859

Colour: Blue Odometer: 112118 km

Engine Capacity: 1580 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm
Front Right Side: West Lake 6 mm
West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,942.16	1,146.32	795.84	40.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	820.00	600.00	220.00	26.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S	2,762.16	1,746.32	1,015.84	36.78
+ GST 7.00/7.00% (S	<b>5\$)</b> 193.35	122.24	71.11	36.78
Nett Amount (S	2,955.51	1,868.56	1,086.95	36.78

**INSPECTION** 

Date of Assignment: 15/11/2021 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 16/11/2021 Inspected At: 59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### REPAIR DETAILS

	•			
டு	$\sim$ $\pm$	0r	$\sim$	$\sim$
~ .				
,		$\sim$ 1	C I I	ce

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Nov 2021)

Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List) **Print Code:** (Unsubmitted, no print-code for SHC8609G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	459.40 FL	*459.40 FL
2	1		*REAR BUMPER REINFORCEMENT	Serviceable	394.80 FL	*- FL
3	2		*REAR BUMPER REINFORCEMENT BRACKET RH/LH	Serviceable	276.20 FL	*- FL
4	1		*REAR BUMPER CENTRE MOULDING	Cracked	451.25 FL	*451.25 FL
5	1		*REAR BUMPER LOWER MOULDING	Cracked	155.00 FL	*155.00 FL
6	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
7	1		*REAR BUMPER FOGLAMP	Cracked	201.50 FL	*201.50 FL
8	1		*REAR BUMPER TOW COVER	Not Necessary	98.80 FL	*- FL
9	1		*REAR BUMPER REVERSE SENSORS	Not Necessary	180.00 F	*- F
10	1		*REAR NO.PLATE WITH TRIM COVER	Cracked	55.00 F	*55.00 F
11_	1		*TOWING FEE		60.00 F	*60.00 F
⊢=⊢ra	inchise	part. L=ListIt		Sub Total (S\$)	2,353.95	1,404.15
			- List Item Discount on L Items	s 20.00/20.00% (S\$)	411.79	257.83
				Total Parts (S\$)	1,942.16	1,146.32
			Report was unsubmitted during this prin	t-out.		

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	400.00	350.00
2	SPRAY PAINTING	New	300.00	250.00
3	R/I REVERSE SENSORS	New	120.00	0.00
		Gross Labour Cost (S\$)	820.00	600.00
		Report was unsubmitted during this print-out.		

< END OF ESTIMATES >