

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT (SUPPLEMENTARY #1)**Our File No:** CS/EQI21011619/R1VF3E2**Date:** 29/11/2021**REFERENCE**

Handling Insurer:	EQ Insurance Company Ltd	Policy No:	DMCPHQ21-001542
Claimant Vehicle No :	SHC8609G	Insured Vehicle No :	GBF9382H
Date of Loss:	13/11/2021	Nature of Claim:	TP
		Claim No:	DM21HO01699

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC8609G		
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Engine No:	G4LEKU421513
Reg. Date:	25/02/2021 (Man. Year: 2019)	Chassis No:	KMHC851CVLU192859
Colour:	Blue	Odometer:	112118 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	118.80	118.80	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	118.80	118.80	0.00	0.00
+ GST 7.00/7.00% (S\$)	8.32	8.32	0.00	0.00
Nett Amount (S\$)	127.12	127.12	0.00	0.00
+ Previous Recommendations (S\$)		0.00		
Nett Liability (S\$)		127.12		

INSPECTION

Date of Assignment:	25/11/2021	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	16/11/2021	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Nov 2021)
Parts:	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC8609G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR SMART KEY ANTENNA	Cracked	40.50 FL	*40.50 FL	
2	1		*REAR BUMPER UNDER COVER LH	Cracked	108.00 FL	*108.00 FL	
F=Franchise part. L=ListItemDisc.							
					Sub Total (\$\$)	148.50	148.50
					- List Item Discount on L Items 20.00/20.00% (\$\$)	29.70	29.70
					Total Parts (\$\$)	118.80	118.80

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >