

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDA 6881G

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DENTED / DEFORMED	1,610.32	1,566.32
1	REAR BUMPER LOWER	SERVICEABLE	410.52	-
2	REAR BUMPER REFLECTORS @\$45.00	NOT NECESSARY	90.00	-
1	REAR BUMPER BEAM	BENT	699.12	681.32
1	REAR BUMPER TOP RETAINER	TWISTED / CRACKED	258.32	255.00
1	REAR BUMPER LICENCE PLATE LAMP	NOT NECESSARY	60.00	-
2	REAR BUMPER SIDE RETAINERS @\$65.00	NECESSARY	130.00	130.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	745.11	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	188.62	-
1	TAILLAMP N/S	SERVICEABLE	585.21	-
	LESS 5% DISCOUNT		-	-131.63
			4,777.22	2,501.01
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR LICENCE PLATE W/HOLDER (SN)	BENT	50.00	40.00
			380.00	290.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REPLACED REVERSE SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY.		120.00	80.00
	TO SPRAY RUST PROOFING.	NOT NECESSARY	60.00	-
	TO RESET & REPROGRAMME SYSTEM.		180.00	50.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF REAR END PANEL.		680.00	500.00

Report Ref No. CS/AGI21011622/Uuf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO PUTTY & SPRAY PAINTING.		880.00	400.00
			2,050.00	1,100.00
	GRAND TOTAL		7,207.22	3,891.01

RECOMMENDED COST OF LUMP SUM REPAIRS	3,100.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/AGI21011622/Uuf3n2

CHUA KANG SENG

Licensed Appraiser