

ASS. J. RY: *Mar 14*

REF:

*CS/AG121011622/Uuf3*ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

C10012459/KY


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

9143

Vehicle: IN / OUT

Date:

Person Contacted:

LTA \$2107

Veh No:

SDA 68816

Yr Regn:

13/3/14

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA1

Make:

Volkswagen Golf

c.c

1395

Colour

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

22310

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WVWZ22AUZEW247563

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55 R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

westlake

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

*25/11/14**2nd 2hrs 4hrs. Net \$753*

25/11/14 d/s \$3100 confirmed with Abn. 3 repair days
(RED \$4107.22; 57%)

Date/Time, File Pass to?

☐

Preli. Report

1) 25/11 TYPIST

☐

Final Report

Date/Time, File Return to?

Days Of Repair: 3

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

2)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

) __ \$ + RS __ \$

) Photos

) Others

Report Format : TP

Lump Sum / ~~1000~~ (\$ 3100

TOTAL

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883
Tel No: 67452063/ 67467158 Fax No: 67458520
Tax Reg No : 200006262D

Submit to insurance not allowed
See
15/11/21
2/5 \$3100
3 days.

VEHICLE No: SDA 6881G

1PC	REAR BUMPER	<i>20/2e</i>	<i>1566.32</i>	\$1,610.32	
1PC	REAR BUMPER LOWER	<i>See</i>		\$410.52	X
2PCS	REAR BUMPER REFLECTORS @\$45.00	<i>n1</i>		\$90.00	X
1PC	REAR BUMPER BEAM	<i>But</i>		\$699.12	
1PC	REAR BUMPER TOP RETAINER	<i>twice</i>	<i>681.32</i>	\$258.32	
1PC	REAR BUMPER LICENCE PLATE LAMP	<i>n1</i>	<i>258.00</i>	\$60.00	X
2PCS	REAR BUMPER SIDE RETAINERS @\$65.00	<i>See</i>		\$130.00	
1PC	REAR END PANEL	<i>R</i>		\$745.11	X
1PC	REAR END PANEL TOP GARNISH	<i>n1</i>		\$188.62	X
1PC	TAILLAMP N/S	<i>See</i>		\$585.21	X
				\$4,777.22	

S.NETT

1SET	REAR BUMPER CLIPS	<i>See</i>	\$50.00	✓
1SET	REAR BUMPER REVERSE SENSOR	<i>should</i>	\$280.00	200
1PC	REAR LICENCE PLATE W/HOLDER	<i>See</i>	\$50.00	40
	TO CHECK WIRING		\$50.00	20
	TO DISMANTLE & REPLACED REVERSE SENSOR		\$80.00	50
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY		\$120.00	80
	TO SPRAY RUST PROOFING	<i>n1</i>	\$60.00	X
	TO RESET & REPROGRAMME SYSTEM		\$180.00	50
	LABOUR FOR PANEL BEATING & REPLACED PARTS		\$680.00	500
	TO PUTTY & SPRAY PAINTING		\$880.00	400
	TOTAL		\$7,207.22	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

22632.64
52
2501.20
2491