



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 7054H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BONNET INNER LOCK	TO REPAIR SEE LABOUR	81.00	-
1	FRONT GRILLE	SERVICEABLE	218.63	-
1	HEADLAMP ASSEMBLY N/S	SERVICEABLE	643.38	-
1	FRONT BUMPER	DENTED / DISTORTED	681.13	681.13
1	FRONT BUMPER CENTRE VENT	CRACKED	201.42	201.42
1	FRONT BUMPER FOG LAMP GARNISH N/S	SERVICEABLE	172.36	-
1	FRONT BUMPER FOG LAMP ASSEMBLY N/S	SERVICEABLE	201.44	-
1	FRONT BUMPER REINFORCEMENT	SERVICEABLE	225.68	-
1	FRONT BUMPER SIDE RETAINER N/S	SERVICEABLE	58.87	-
1	FRONT FENDER N/S	TO REPAIR SEE LABOUR	434.44	-
1	FRONT FENDER INNER SHIELD N/S	SERVICEABLE	58.01	-
	LESS 10% DISCOUNT		-	-88.26
			2,976.36	794.29
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT BUMPER CLIP / FASTENER (SN)	ESSENTIAL	50.00	30.00
1	FRONT FENDER INNER SHIELD CLIP / FASTENER N/S (SN)	NOT NECESSARY	30.00	-
1	FRONT BUMPER LICENCE PLATE C/W HOLDER (SN)	INTACT	45.00	-
			125.00	30.00
<u>LABOUR</u>				
	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS, RECONNECT & CHECK FUNCTIONS INCLUDING TO FOCUS HEADLAMPS.	NOT NECESSARY	50.00	-
	TO DISMANTLE / INSTALL AIRCONDITIONER CONDENSER & RADIATOR ASSEMBLY, PIPES & HOSES ETC TO FACILITATE REPAIRS & REFILL WITH REFRIGERANT [CLIMATISER R134A SPECIFICATION] & COOLANT RESPECTIVELY.	NOT NECESSARY	180.00	-

Report Ref No. CS3/LPC18019875/R1tf3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE / RENEW THE FRONT ACCIDENT DAMAGED PORTIONS. TO HEAT, KNOCK-OUT, RESHAPE, STRAIGHTEN, ORIENTATE & ALIGN BONNET & ITS INNER REINFORCEMENT, BONNET HINGE O/S & N/S, BONNET INNER LOCK / BRIDGE PANEL, FRONT BUMPER REINFORCEMENT, FRONT FENDER N/S, FRONT SUPPORT PANEL ETC. TO SYMMETRICAL DIMENSIONS. INCLUSIVE OF THE REPAIR OF BONNET INNER LOCK AND FRONT FENDER N/S.		850.00	250.00
	TO PUTTY / PRIMER APPLICATION AND SPRAY PAINTING INCLUDING TOUCH-UP AFFECTED AREAS WITH POLYURETHANE PAINT. }		850.00	200.00
	TO DO RUSTPROOFING AND CAVITIES PRESERVATION TO THE REPLACED AND REPAIRED PANELS. }		-	-
			1,930.00	450.00
GRAND TOTAL			5,031.36	1,274.29
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,000.00

Report Ref No. CS3/LPC18019875/R1tf3e2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.