

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21011623/UGA3Q2**Date:** 29/04/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SNB1343C**Insured Vehicle No :** SLP5367H

Date of Loss: 14/10/2021

Nature of Claim:

TP

Claim No: 3257232420SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SNB1343C**

Make & Model: TOYOTA CAMRY, 2.5 4DR SEDAN (A)

Engine No: A25A5614562

Reg. Date: 30/07/2021 (Man. Year: 2021)

Chassis No: JTNB23HK303101425

Colour: Black

Odometer: 23647 km

Engine Capacity: 2487 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17

Rear Tyre Size: 215/55 R17

Front Left Side: Michelin 8 mm

Rear Left Side: Michelin 8 mm

Front Right Side: Michelin 8 mm

Rear Right Side: Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,106.27	3,717.30	1,388.97	27.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,720.00	820.00	900.00	52.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,826.27	4,537.30	2,288.97	33.53
Approved Total (Overridden) (S\$)		3,600.00		
(S\$)	6,826.27	3,600.00	3,226.27	47.26
+ GST 7.00/7.00% (S\$)	477.84	252.00	225.84	47.26
Nett Amount (S\$)	7,304.11	3,852.00	3,452.11	47.26
+ Loss of Use (5.0 x S\$80.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		31.00		
Nett Liability (S\$)		4,283.00		
Global Sum Settlement (S\$)		4,250.00		

INSPECTION

Date of Assignment: 15/11/2021

Date Inspected: 16/11/2021 Inspected At:

Focus Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #02-48/50 Autobay
Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER -R/H	Repair	768.20 FL	*- FL
2	1		*FRONT FENDER DUST COVER-R/H	Not Necessary	198.40 FL	*- FL
3	6		*FRONT FENDER DUST COVER CLIPS -R/H	Not Necessary	77.40 FL	*- FL
4	1		*FRONT HEADLAMP -R/H	Cracked	2,690.76 FL	*2,690.70 FL
5	1		*FRONT BUMPER	Distorted	965.20 FL	*965.20 FL
6	1		*FRONT BUMPER SIDE RETAINER -R/H	Cracked	68.40 FL	*68.40 FL
7	2		*FRONT BUMPER SIDE CLIP -RH	Not Necessary	25.80 FL	*- FL
8	1		*FRONT BUMPER MOULDING -RH	Cracked	367.20 FL	*367.20 FL
9	2		*FRONT BUMPER SENSOR -RH	Shorted (1 PCS ONLY)	792.40 FL	*381.60 FL
10	1		*FRONT BUMPER GRILLE	Twisted / Cracked	498.20 FL	*483.30 FL
11	1		*FRONT BUMPER TOP GRILLE	Not Necessary	356.40 FL	*- FL
					Sub Total (\$\$)	6,808.36 4,956.40
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,702.09 1,239.10
					Total Parts (\$\$)	5,106.27 3,717.30

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	850.00	300.00
2	CHECK WIRING	New	60.00	20.00
3	RUST PROOFING	New	60.00	0.00
4	SPRAY PAINTING	New	750.00	500.00
Gross Labour Cost (\$\$)			1,720.00	820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >