

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21011624/TEA3Q2**Date:** 28/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100436990-06
Claimant Vehicle No :	SH7012C	Insured Vehicle No :	SKW6642G
Date of Loss:	13/11/2021	Nature of Claim:	TP
		Claim No:	5596915487SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH7012C		
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT (A)	Engine No:	2ZRR963118
Reg. Date:	25/05/2017 (Man. Year: 2017)	Chassis No:	JTDKB3FU103556797
Colour:	Blue	Odometer:	508960 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,210.05	1,148.77	61.28	5.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,400.00	880.00	520.00	37.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,610.05	2,028.77	581.28	22.27
Approved Total (Overridden) (S\$)		1,600.00		
(S\$)	2,610.05	1,600.00	1,010.05	38.70
+ GST 7.00/7.00% (S\$)	182.70	112.00	70.70	38.70
Nett Amount (S\$)	2,792.75	1,712.00	1,080.75	38.70
+ Loss of Use (1.0 x S\$50.00/day) (S\$)		50.00		
+ Car Rental (1.0 x S\$125.40/day) (S\$)		125.40		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,889.40		

INSPECTION

Date of Assignment:	15/11/2021	
Date Inspected:	15/11/2021	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FRONT BUMPER	Deformed	499.90 FL	*499.90 FL
2	1		*FENDER SUB-ASSY FRONT LH	Bent	945.30 FL	*945.30 FL
3	1		*EMBLEM SIDE PANEL (HYBRID)	Necessary	86.50 FL	*86.50 FL
4	1		*SUPPORT FRONT BUMPER SIDE	Not Necessary	81.70 FL	*- FL
					Sub Total (\$\$)	1,613.401,531.70
					- List Item Discount on L Items 25.00/25.00% (\$\$)	403.35382.93
					Total Parts (\$\$)	1,210.051,148.77

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	750.00	350.00
2	SPRAYPAINT CHARGE	New	600.00	500.00
3	TUFF COAT AFFECTED PARTS	New	50.00	30.00
Gross Labour Cost (\$)			1,400.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >