

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21011626/VPA3Q2**Date:** 27/02/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210117708
Claimant Vehicle No :	SJM865J	Insured Vehicle No :	SKC3457A
Date of Loss:	11/11/2021	Nature of Claim:	TP
		Claim No:	0744928823SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJM865J		
Make & Model:	MITSUBISHI LANCER, 2.0 MIVEC L GT (M)	Engine No:	4B11BX4577
Reg. Date:	22/12/2008 (Man. Year: 2008)	Chassis No:	JMYSNCY4A8U001147
Colour:	Orange	Odometer:	241473 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40Z R18	Rear Tyre Size:	225/40Z R18
Front Left Side:	Kumho 5 mm	Rear Left Side:	Kumho 5 mm
Front Right Side:	Kumho 5 mm	Rear Right Side:	Kumho 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,175.80	784.72	391.08	33.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,420.00	530.00	890.00	62.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	2,595.80	1,314.72	1,281.08	49.35
Approved Total (Overridden) (\$\$)		1,050.00		
Nett Amount (\$\$)	2,595.80	1,050.00	1,545.80	59.55
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment:	15/11/2021	
Date Inspected:	14/02/2022	Inspected At: Hup Ley Huat Motor Spray Painting Services BLK 1 KAKI BUKIT AVE 6 #01-35 Singapore 409793
Estimated Period of Repair:	2.0 days	

Adjuster: Thevan Thomas Karthikesavan**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	815.00 FS	*500.00 FS
2	1		*REAR BUMPER SIDE RETAINER LH	Necessary	60.80 F	*60.80 FL
3	1		*REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
4	1		*REAR REVERSE SENSOR	Cut	250.00 FS	*200.00 FS
					Sub Total (\$\$)	1,175.80 790.80
					- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00 6.08
					Total Parts (\$\$)	1,175.80 784.72

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TUFF COAT AFFECTED AREAS	New	100.00	30.00
2	TO SPRAY PAINT INCLUDE POLISHING AND WAXING ON THE CHARGES BODY PARTS ,REPAIR BODY PORTIONS WHERE CONSISTENT TO THE ACCIDENT	New	600.00	250.00
3	TO PROVIDE LABOUR CHARGES ,WORKMANSHIP TO REALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT	New	600.00	250.00
4	TO REMOVE AND REFIT WIRING FOR REAR SENSOR	New	120.00	0.00
Gross Labour Cost (S\$)			1,420.00	530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >