

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21011628/UGA3Q2**Date:** 09/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100501624
Claimant Vehicle No :	SLV4568U	Insured Vehicle No :	SLL3315S
Date of Loss:	13/11/2021	Nature of Claim:	TP
		Claim No:	9341912967SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV4568U	Engine No:	1NZR494261
Make & Model:	TOYOTA COROLLA AXIO, 1.5 HYBRID CVT (A)	Chassis No:	NKE1657144212
Reg. Date:	29/12/2017 (Man. Year: 2017)	Odometer:	277083 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Davanti 6 mm	Rear Left Side:	Davanti 6 mm
Front Right Side:	Davanti 6 mm	Rear Right Side:	Davanti 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,827.01	2,181.42	2,645.59	54.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,640.00	1,330.00	310.00	18.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,467.01	3,511.42	2,955.59	45.70
Approved Total (Overridden) (S\$)		2,800.00		
Nett Amount (S\$)	6,467.01	2,800.00	3,667.01	56.70
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,107.45		

INSPECTION

Date of Assignment:	15/11/2021	
Date Inspected:	16/11/2021	Inspected At: Trident Auto Service Centre Pte Ltd (HQ) 8 Kaki bukit Ave 4 #02-44 Premier Singapore 415875
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Repair	798.50 FL	*- FL
2	1		*REAR BOOT HINGES	Not Necessary	145.80 FL	*- FL
3	1		*REAR BOOT LOCK	Serviceable	185.15 FL	*- FL
4	1		*REAR BOOT RUBBER	Torn	211.50 FL	*211.50 FL
5	1		*REAR BOOT AXIO EMBLEM	Necessary	68.50 FL	*68.50 FL
6	1		*REAR BOOT CAROLLA EMBLEM	Necessary	62.60 FL	*62.60 FL
7	1		*REAR BOOT HYBRID EMBLEM	Necessary	78.00 FL	*78.00 FL
8	1		*REAR LEFT TAILLAMP	Not Necessary	481.30 FL	*- FL
9	1		*REAR RIGHT TAILLAMP	Cracked	481.30 FL	*481.30 FL
10	1		*REAR END PANEL	Dented	608.80 FL	*608.80 FL
11	1		*REAR END PANEL INNER GARNISH	Twisted	177.73 FL	*177.73 FL
12	1		*REAR BUMPER	Distorted	1,014.30 FL	*655.10 FL
13	1		*REAR BUMPER TOP BRACKETS	O/S Bent	175.80 FL	*87.90 FL
14	2		*REAR BUMPER REFLECTORS	Not Necessary	164.00 FL	*- FL
15	2		*REAR BUMPER SIDE RETAINERS	Bent / Necessary	143.80 FL	*143.80 FL
16	1		*REAR EXHAUST MUFFER	Not Necessary	985.60 FL	*- FL
17	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*50.00 FS
18	1		*SET REAR NUMBER PLATE WITH HOLDER	Serviceable	60.00 FS	*- FS
19	1		*SET REVERSE SENSOR	Shorted	350.00 FS	*200.00 FS
					Sub Total (\$\$)	6,272.68 2,825.23
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,445.67 643.81
					Total Parts (\$\$)	4,827.01 2,181.42

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER ,REAR BOOTLID ,END PANEL TO REPAIR AND RE-ALIGN ON ALL ACCIDENT AFFECTED AREAS	New	800.00	600.00
2	TO PUTTY AND RESPRAY ON ACCIDENT PORTION	New	700.00	680.00
3	TO CHECK WIRING	New	80.00	20.00
4	TO APPLY ANTI-RUST CORROSION ON AFFECTED AREAS	New	60.00	30.00
Gross Labour Cost (\$\$)			1,640.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >