

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21011630/APA3Q2**Date:** 30/03/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SJQ865M**Insured Vehicle No :** SKA382L

Date of Loss: 09/11/2021

Nature of Claim: TP Claim No: 6466565042SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJQ865M**

Make & Model: OPEL INSIGNIA GRANDSPORT B15XHT, 1.5 (A)

Engine No: B1173348HAKX0495

Reg. Date: 26/08/2019 (Man. Year: 2018)

Chassis No: W0VZT6EB8J1089393

Colour: Grey

Odometer: 40518 km

Engine Capacity: 1490 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45 R18

Rear Tyre Size: 245/45 R18

Front Left Side: Hankook 6 mm

Rear Left Side: Hankook 6 mm

Front Right Side: Hankook 6 mm

Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,889.60	45.00	14,844.60	99.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,780.00	1,280.00	4,500.00	77.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	20,669.60	1,325.00	19,344.60	93.59
+ GST 7.00/7.00% (S\$)	1,446.87	92.75	1,354.12	93.59
Nett Amount (S\$)	22,116.47	1,417.75	20,698.72	93.59
+ Car Rental (2.0 x S\$100.00/day + 7.00% GST) (S\$)		214.00		
		Nett Liability (S\$)	1,631.75	
		Global Sum Settlement (S\$)	1,600.00	

INSPECTION

Date of Assignment: 12/11/2021

Date Inspected: 12/11/2021

Inspected At:

1st Autoworks Pte Ltd (HQ)

23 Kaki Bukit Ave 4, #04-01

Singapore 415933

Estimated Period of Repair: 2.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Not Necessary	2,364.00 FL	*- FL
2	1		*BOOT LID EMBLEM	Not Necessary	555.00 FL	*- FL
3	1		*BOOT LID LETTERING INSIGNIA	Not Necessary	167.00 FL	*- FL
4	1		*BOOT LID LETTERING TURBO	Not Necessary	167.00 FL	*- FL
5	1		*RHR BOOTLID LAMP	Not Necessary	596.00 FL	*- FL
6	1		*LHR BOOTLID LAMP	Not Necessary	596.00 FL	*- FL
7	1		*RR TAILGATE LOCK	Not Necessary	354.00 FL	*- FL
8	1		*RR TAILGATE LOCK CATCHER -STRIKER	Not Necessary	139.00 FL	*- FL
9	1		*RR TAILGATE LOCK KEYLESS RECEIVER SENSOR	Not Necessary	267.00 FL	*- FL
10	1		*RR BUMPER	Repair	1,338.00 FL	*- FL
11	1		*RR BUMPER TOW COVER	Not Necessary	148.00 FL	*- FL
12	1		*RR BUMPER SIDE RETAINER RH (INNER) -GUIDE	Not Necessary	130.00 FL	*- FL
13	1		*RR BUMPER SIDE RETAINER RH (OUTER) -BRACKET	Not Necessary	125.00 FL	*- FL
14	1		*RR BUMPER CENTER RETAINER	Not Necessary	130.00 FL	*- FL
15	1		*RR BUMPER SIDE RETAINER LH (INNER) -GUIDE	Not Necessary	130.00 FL	*- FL
16	1		*RR BUMPER SIDE RETAINER LH (OUTER) -BRACKET	Not Necessary	125.00 FL	*- FL
17	1		*RR BUMPER LOW BRACKET RH	Not Necessary	110.00 FL	*- FL
18	1		*RR BUMPER LOW BRACKET LH	Not Necessary	110.00 FL	*- FL
19	1		*RR BUMPER REINFORCEMENT	Not Necessary	519.00 FL	*- FL
20	1		*RR BUMPER LOW GARNISH	Repair	366.00 FL	*- FL
21	4		*RR BUMPER REVERSE SENSOR	Not Necessary	1,120.00 FL	*- FL
22	1		*RR BUMPER BLIND SPOT SENSOR	Not Necessary	510.00 FL	*- FL
23	1		*RR BUMPER REVERSE SENSOR RUBBER SEAL	Not Necessary	14.00 FL	*- FL
24	1		*RR BUMPER REVERSE SENSOR WIRE HARNESS	Not Necessary	410.00 FL	*- FL
25	1		*RR BUMPER REFLECTOR RH	Not Necessary	123.00 FL	*- FL
26	1		*RR BUMPER REFLECTOR LH	Not Necessary	123.00 FL	*- FL
27	1		*RR BUMPER NUMBER PLATE LAMP	Not Necessary	124.00 FL	*- FL
28	1		*RR BLIND SPOT CONTROL UNIT RH	Not Necessary	572.00 FL	*- FL
29	1		*RR BLIND SPOT CONTROL UNIT BRACKET RH	Not Necessary	122.00 FL	*- FL
30	1		*RR REVERSE CAMERA	Not Necessary	531.00 FL	*- FL
31	1		*RR BUMPER BODY KIT RH	Not Necessary	1,335.00 FL	*- FL
32	1		*RR BUMPER BODY KIT LH	Not Necessary	1,335.00 FL	*- FL
33	1		*RR TAILLAMP RH	Not Necessary	727.00 FL	*- FL
34	1		*RR TAILLAMP LH	Not Necessary	727.00 FL	*- FL
35	10		*REAR NUMBER PLATE & BRACKET	Cracked	45.00 FS	*45.00 FS
36	1		*SET REAR BUMPER CLIP	Not Necessary	65.00 FS	*- FS
37	12		*INNER BOOTLID TRIM CLIPS	Not Necessary	71.50 FS	*- FS
38	1		*REAR END PANEL INSULATION SEAL	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	16,510.50	45.00
- List Item Discount on L Items 10.00/10.00% (\$)	1,620.90	0.00
Total Parts (\$)	14,889.60	45.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION ,TO PANEL BEATING ,RESHAPE STRAIGHTEN ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	2,500.00	650.00
2	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA	New	2,300.00	550.00
3	TO CONDUCT ANTI RUST OF UNDER CARRIAGE TUFF COAT	New	250.00	0.00
4	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	80.00	0.00
5	REMOVE AND REFIX SEAT CUSHION /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIRS	New	250.00	0.00
6	TO REMOVE AND REFIX REVERSE SENSOR AND CONDUCT TEST	New	80.00	80.00
7	TO CONDUCT TRANSFER OF PARTS FROM OLD BOOTLID TO NEW BOOTLID	New	80.00	0.00
8	TO CONDUCT WATER LEAKAGE TEST AFTER REPAIRS OF VEHICLE	New	80.00	0.00
9	REMOVE AND REPLACE REVERSE SENSOR (LABOUR)	New	80.00	0.00
10	REMOVE AND REPLACE REVERSE CAMERA (LABOUR)	New	80.00	0.00
Gross Labour Cost (\$\$)			5,780.00	1,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >