

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21011633/UPS3Q2**Date:** 17/01/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SMJ7106B**Insured Vehicle No :** SGK93R

Date of Loss: 11/11/2021

Nature of Claim: TP Claim No: 0798295430SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMJ7106B**

Make & Model: KIA CARENS, 1.7 DCT (A)

Engine No: D4FDJD024169

Reg. Date: 18/03/2019 (Man. Year: 2018)

Chassis No: KNAHU815VJ7211312

Colour: Grey

Odometer: 146562 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Comfortmax 6 mm

Rear Left Side: Comfortmax 6 mm

Front Right Side: Comfortmax 6 mm

Rear Right Side: Comfortmax 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,968.60	3,365.30	2,603.30	43.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,750.00	2,110.00	640.00	23.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,718.60	5,475.30	3,243.30	37.20
Approved Total (Overridden) (S\$)		4,350.00		
(S\$)	8,718.60	4,350.00	4,368.60	50.11
+ GST 7.00/7.00% (S\$)	610.30	304.50	305.80	50.11
Nett Amount (S\$)	9,328.90	4,654.50	4,674.40	50.11
+ Car Rental (7.0 x S\$77.00/day) (S\$)		539.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,195.50		

INSPECTION

Date of Assignment: 15/11/2021

Date Inspected: 15/11/2021

Inspected At:

Tan Lim Motor Pte Ltd (Defu)

1 Defu Lane 6

Singapore 539365

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	549.00 FL	*549.00 FL
2	8		*REAR BUMPER CLIPS	Necessary	28.00 FL	*28.00 FL
3	1		*REAR BUMPER CENTRE PAD	Distorted	189.00 FL	*189.00 FL
4	1		*REAR BUMPER LOWER	Cut	179.00 FL	*179.00 FL
5	1		*REAR BUMPER REVERSE SENSOR	Shorted	162.00 FL	*162.00 FL
6	2		*REAR BUMPER SIDE RETAINER	Not Necessary	56.00 FL	*- FL
7	1		*REAR BUMPER REFLECTOR	O/S Cracked / N/SNot Necessary	232.00 FL	*116.00 FL
8	1		*REAR BUMPER REINFORCEMENT	Cracked	367.00 FL	*341.00 FL
9	2		*REAR BUMPER BRACKET	Bent / Twisted	168.00 FL	*168.00 FL
10	2		*REAR BUMPER LOWER BRACKET	Not Necessary	54.00 FL	*- FL
11	2		*REAR BUMPER TOP BRACKET	Not Necessary	50.00 FL	*- FL
12	6		*REAR BUMPER HOLDER (NPA)	Not Necessary	0.00 FL	*- FL
13	1		*TAILGATE LID	Badly Dented	1,088.00 FL	*1,088.00 FL
14	1		*TAILGATE LID LOCK	Shorted	112.00 FL	*112.00 FL
15	1		*TAILGATE LID INNER GARNISH	Not Necessary	153.00 FL	*- FL
16	1		*TAILGATE LID WEATHERSTRIP	Twisted	115.00 FL	*115.00 FL
17	1		*TAILGATE LID NUMBER PLATE GARNISH (NPA)	Not Necessary	0.00 FL	*- FL
18	1		*TAILGATE LID NUMBER PLATE GARNISH CHROME	Not Necessary	95.00 FL	*- FL
19	1		*TAILGATE LID NUMBER PLATE LAMP	Not Necessary	85.00 FL	*- FL
20	1		*TAILGATE LID KEYLESS SWITCH	Not Necessary	115.00 FL	*- FL
21	1		*TAILGATE LID KEYLESS SWITCH ANTENA	Not Necessary	95.00 FL	*- FL
22	1		*TAIL LAMP	Not Necessary	770.00 FL	*- FL
23	2		*TAIL LAMP CLIPS	Not Necessary	12.00 FL	*- FL
24	1		*REAR END PANEL	Badly Dented	611.00 FL	*611.00 FL
25	1		*REAR END PANEL TOP GARNISH	Not Necessary	123.00 FL	*- FL
26	1		*REAR BOOT TOOLS COMPARTMENT	Not Necessary	515.00 FL	*- FL
27	1		*REAR BOOT TOOLS COMPARTMENT FLOOR BOARD TOP	Not Necessary	279.00 FL	*- FL
28	2		*REAR BOOT TOOLS COMPARTMENT FLOOR BOARD SIDE	Not Necessary	258.00 FL	*- FL
29	1		*TAILGATE LID CARENS BADGE	Necessary	28.00 FL	*28.00 FL
30	1		*TAILGATE LID CRDI BADGE	Necessary	31.00 FL	*31.00 FL
31	1		*TAILGATE LID CENTRE EMBLEM BADGE	Not Necessary	35.00 FL	*- FL
32	1		*REAR LICENCE PLATE	Not Necessary	50.00 FS	*- FS
33	1		*REAR WINDSCREEN SEALANT	Necessary	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,624.00	3,737.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	655.40	371.70
Total Parts (\$\$)	5,968.60	3,365.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TRANSFER OF TAILGATE FITTINGS ,FIXTURE AND PERFORM WATERSEEPAGE TEST	New	100.00	60.00
2	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	140.00	120.00
3	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	80.00	20.00
4	TO RUST-PROOFING OF THE AFFECTED AREAS	New	250.00	60.00
5	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	80.00	50.00
6	TO TRANSFER OF TYRE ,RIM AND ON WHEEL BALACING	New	100.00	0.00
7	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,000.00	850.00
8	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,000.00	950.00
Gross Labour Cost (\$)			2,750.00	2,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >