

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21011634/RPA3Q2**Date:** 30/06/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : GBK2316U**Insured Vehicle No :** SLH1473C

Date of Loss: 23/10/2021

Nature of Claim:

TP

Claim No: 2349009917SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBK2316U**

Make & Model: TOYOTA HIACE, 2.8 D GL (A)

Engine No: 1GD8484785

Reg. Date: 27/02/2020 (Man. Year: 2019)

Chassis No: JTFRA3APX08008097

Colour: White

Odometer: 49868 km

Engine Capacity: 2755 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/70 R16

Rear Tyre Size:

215/70 R16

Front Left Side: Sailwin 6 mm

Rear Left Side:

Sailwin 6 mm

Front Right Side: Sailwin 6 mm

Rear Right Side:

Sailwin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,680.24	1,035.07	9,645.17	90.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,360.00	1,310.00	2,050.00	61.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,040.24	2,345.07	11,695.17	83.30
Approved Total (Overridden) (S\$)		1,850.00		
(S\$)	14,040.24	1,850.00	12,190.24	86.82
+ GST 7.00/7.00% (S\$)	982.82	129.50	853.32	86.82
Nett Amount (S\$)	15,023.06	1,979.50	13,043.56	86.82
+ Car Rental (3.0 x S\$100.00/day + 7.00% GST) (S\$)		321.00		
Nett Liability (S\$)		2,300.50		

INSPECTION

Date of Assignment: 15/11/2021

Date Inspected: 16/11/2021 Inspected At:

19 Jurong Port Rd Singapore 619093
Repairer: WESTPOINT AUTOMOTIVE
SOLUTIONS PTE. LTD. (HQ)

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Scratched	410.70 FL	*410.70 FL
2	1		*REAR SIDE BUMPER	Scratched	210.00 FL	*210.00 FL
3	1		*REAR TAIL LAMP	Cracked	399.40 FL	*399.40 FL
4	1		*REAR SIDE BUMPER SUPPORT	Not Necessary	85.90 FL	*- FL
5	1		*REAR QUARTER PANEL OUTER	Repair	489.40 FL	*- FL
6	1		*REAR QUARTER PANEL INNER	Not Necessary	780.10 FL	*- FL
7	1		*REAR QUARTER WHEEL HOUSING ASSY	Not Necessary	588.30 FL	*- FL
8	1		*BACK DOOR ORENING REINFORCEMENT	Not Necessary	789.10 FL	*- FL
9	2		*REAR INNER TRIM PANEL	Not Necessary	1,237.80 FL	*- FL
10	1		*REAR INNER TRIM	Not Necessary	1,050.40 FL	*- FL
11	2		*REAR SLIDING DOOR ASSY	Not Necessary	4,360.80 FL	*- FL
12	1		*REAR SIDE DOOR TRIM	Not Necessary	680.40 FL	*- FL
13	1		*REAR FLOOR PANEL	Not Necessary	1,180.50 FL	*- FL
14	1		*REAR BUMPER BRACKET CLIPS	Necessary	50.00 FS	*30.00 FS
15	1		*REAR SIDE BUMPER BRACKET /CLIPS	Not Necessary	50.00 FS	*- FS
16	1		*REAR TAIL LAMP CLIPS	Necessary	50.00 FS	*20.00 FS
17	1		*REAR QUARTER PANEL SEALANT	Not Necessary	80.00 FS	*- FS
18	1		*REAR SIDE DOOR BRACKET /CLIPS	Not Necessary	80.00 FS	*- FS
19	1		*REAR FLOOR PANEL SEALANT	Not Necessary	100.00 FS	*- FS
20	1		*REAR FLOOR PANEL MOULDING	Not Necessary	80.00 FS	*- FS
21	1		*COMPANY STICKER	Necessary	300.00 FS	*200.00 FS
22	1		*SUNDRIES	Necessary	80.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,132.80	1,290.10
- List Item Discount on L Items 20.00/25.00% (\$\$)	2,452.56	255.03
Total Parts (\$\$)	10,680.24	1,035.07

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPAIR ,REPLACE & ALIGN REAR ACCIDENT DAMAGED AREAS	New	1,500.00	600.00
2	TO PUTTY AND RESPRAY ALL AFFECTED PORTIONS	New	1,200.00	600.00
3	TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION	New	100.00	30.00
4	TO RUST PROOF ACCIDENT AFFECTED PORTIONS	New	120.00	0.00
5	TO R&R REAR LUGGAGE COMPARTMENT	New	20.00	20.00
6	TO R&R REAR REVERSE SENSORS AND CHECK FUNCTION	New	120.00	60.00
7	TO CONDUCT WHEEL ALIGNMENT CHECK (BEFORE & AFTER)	New	100.00	0.00
8	TO R&R REAR INTERIOR TRIMS TO FACILITATE REPAIRS	New	100.00	0.00
9	TO CHECK REAR SEEPAGE AFTER REPAIRS	New	100.00	0.00
Gross Labour Cost (\$)			3,360.00	1,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >