2/14/22, 2:06 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21011636/TGS3Q2

14/02/2022 Date:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7210020232 **Claimant Vehicle** SHC7024A Insured Vehicle No: SMY2788L

No:

Date of Loss: 14/11/2021 Nature of Claim: TP Claim No: 7745339406SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC7024A**

Make & Model: HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A) Engine No: D4FDGU651823

Reg. Date: 17/03/2016 (Man. Year: 2015) Chassis No: KMHLB41UMGU085582

Colour: Odometer: 1213420 km Yellow

Engine Capacity: 1685 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16 Front Left Side: Rear Left Side: West Lake 6 mm West Lake 6 mm Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,151.70	645.70	1,506.00	69.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	960.00	560.00	400.00	41.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,111.70	1,205.70	1,906.00	61.25
Approved Total (Overridden) (S\$)		950.00		
(S\$)	3,111.70	950.00	2,161.70	69.47
+ GST 7.00/7.00% (S\$)	217.82	66.50	151.32	69.47
Nett Amount (S\$)	3,329.52	1,016.50	2,313.02	69.47
+ Loss of Use (2.0	x S\$50.00/day) (S\$)	100.00		
+ Car Rental (2.0 x	S\$110.67/day) (S\$)	221.34		
+ D	oc/Search Fee (S\$)	2.00		
	Nett Liability (S\$)	1,339.84		
Global S	um Settlement (S\$)	1,300.00		

INSPECTION

Date of Assignment: 15/11/2021

ComfortDelGro Engineering Pte Ltd (Loyang) Date Inspected: 15/11/2021 Inspected At: 59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

MOHD TAUFIKH BIN HAMID Chong Pui Lin Adjuster: Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER COVER	Deformed	553.00 FL	*553.00 FL	
2	1		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL	
3	1		*REAR BUMPER SIDE BRACKET RH	Not Necessary	35.60 FL	*-FL	
4	1		*REAR BUMPER REFLECTOR LAMP RH	Not Necessary	32.00 FL	*- FL	
5	1		*EXHAUST SILENCER RH	Not Necessary	967.70 FL	*- FL	
6	1		*EXHAUST PIPE CENTRE	Not Necessary	730.10 FL	*- FL	
7	1		*EXHAUST PIPE HANGER	Not Necessary	117.10 FL	*- FL	
8	1		*REAR BUMPER REVERSE SENSOR	Not Working	135.70 FS	*135.70 FS	
9 E=Era	1 Inchise	nart S=SncN	*REAR BUMPER RUBBER MAT ett. L=ListItemDisc.	Necessary	50.00 FS	*50.00 FS	
1 -110	111011130	part. 0-oport	Sa. E-Estrembise.	Sub Total (S\$)	2,643.20	760.70	
	- List Item Discount on L Items 20.00/20.00% (S\$)			491.50	115.00		
				Total Parts (S\$)	2,151.70	645.70	
	Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	PANEL BEATING	New	450.00	280.00
2	SPRAY PAINTING CHARGE	New	300.00	250.00
3	REMOVE/REFIX EXHAUST PIPE	New	150.00	0.00
4	REMOVE/REFIX REVERSE SENSOR	New	60.00	30.00
		Gross Labour Cost (S\$)	960.00	560.00

Report was unsubmitted during this print-out. < END OF ESTIMATES >