

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21011638/UQY3N2**Date:** 30/11/2021REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00200672100
Claimant Vehicle No :	SLZ7246H	Insured Vehicle No :	SKV2410R
Date of Loss:	14/11/2021	Nature of Claim:	TP
		Claim No:	SNM21D206548/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ7246H	Engine No:	LEB6548705
Make & Model:	HONDA SHUTTLE, 1.5 (A)	Chassis No:	GP71207055
Reg. Date:	16/05/2018 (Man. Year: 2018)	Odometer:	327644 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,567.36	4,757.84	4,809.52	50.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,330.00	1,880.00	1,450.00	43.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,897.36	6,637.84	6,259.52	48.53
Approved Total (Overridden) (\$\$)		5,300.00		
Nett Amount (\$\$)	12,897.36	5,300.00	7,597.36	58.91

INSPECTION

Date of Assignment:	15/11/2021	
Date Inspected:	16/11/2021	Inspected At:
Estimated Period of Repair:	5.0 days	

130 BEDOK RESERVOIR ROAD,
#08-1339,EUNOS SPRING
SINGAPORE 470130
REPAIRER:ZOOM AUTOWERKS PTE LTD

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 29 Nov 2021)	
Parts:	N/A	HONDA SHUTTLE 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLZ7246H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Repair	1,150.00 FL	*- FL
2	1		*FRONT INNER ARCH PANEL N/S	Dented	224.00 FL	*224.00 FL
3	1		*FRONT HEADLAMP LH	Cracked	2,250.00 FL	*2,227.70 FL
4	1		*FRONT GRILLE	Not Necessary	395.00 FL	*- FL
5	1		*FRONT GRILLE CHROME	Not Necessary	260.00 FL	*- FL
6	1		*FRONT GRILLE LOGO	Not Necessary	55.00 FL	*- FL
7	1		*FRONT BUMPER	Distorted	1,400.00 FL	*862.90 FL
8	1		*FRONT BUMPER CLIP (1 SET)	Necessary	50.00 FL	*50.00 FL
9	1		*FRONT BUMPER LOWER GRILLE	Torn	140.00 FL	*140.00 FL
10	1		*FRONT BUMPER REINFORCEMENT	Bent	420.90 FL	*420.80 FL
11	2		*FRONT BUMPER SIDE RETAINERS	Cracked/Necessary	90.00 FL	*90.00 FL
12	1		*FRONT FENDER-LH	Dented/Buckled	580.00 FL	*368.40 FL
13	1		*FRONT FENDER INNER SHIELD	Torn	168.00 FL	*168.00 FL
14	1		*FRONT FENDER INNER SHIELD CLIP (1 SET)	Necessary	50.00 FL	*50.00 FL
15	1		*FRONT FENDER HYBRID EMBLEM	Necessary	48.00 FL	*48.00 FL
16	1		*FRONT WIPER TANK	Not Necessary	135.00 FL	*- FL
17	1		*FRONT WHEEL HUB	Damaged	138.30 FL	*138.30 FL
18	1		*FRONT WHEEL BEARING	Damaged	168.30 FL	*168.30 FL
19	1		*FRONT SHOCK ABSORBER	Not Necessary	420.30 FL	*- FL
20	1		*FRONT KNUCKLE ARM	Warped	330.60 FL	*330.60 FL
21	1		*FRONT LOWER ARM	Bent	285.30 FL	*285.30 FL
22	1		*FRONT TIE ROD	Not Necessary	105.60 FL	*- FL
23	1		*STABILIZER BAR	Not Necessary	228.00 FL	*- FL
24	1		*STABILIZER BAR LINK	Not Necessary	117.60 FL	*- FL
25	1		*FRONT DRIVE SHAFT	Not Necessary	1,186.80 FL	*- FL
26	1		*FRONT TYRE	Serviceable	400.00 FS	*- FS
27	1		*FRONT WHEEL RIM-LH	Cut/Bent	850.00 FS	*300.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,646.70	5,872.30
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,079.34	1,114.46
Total Parts (\$\$)	9,567.36	4,757.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING	New	80.00	20.00
2	TO REMOVE AND REFIT FRONT UNDERCARRIAGE	New	350.00	120.00
3	TO CONDUCT WHEEL ALIGNMENT	New	150.00	80.00
4	TO APPLY UNDERCOATING	New	150.00	60.00
5	PANEL BEATING	New	1,400.00	600.00
6	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,200.00	1,000.00
Gross Labour Cost (\$)			3,330.00	1,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >