LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited Our File No: CS/ICS21011639/GQF3E2

10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600

Date: 23/03/2022

REFERENCE

Insured/Claimant: CHONG WAI MENG Policy No: MPC20P00200400

Date of Loss: 11/11/2021 Nature of Claim: OD Claim No: DMPC2100399H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SFG9981B

Make & Model: LEXUS RX270, 2.7 (A) Engine No: 1AR0428671

Reg. Date: 18/12/2010 (Man. Year: 2010) Chassis No: JTJZA11A002002253

Colour: Black Odometer: 216588 km

Engine Capacity: 2672 cc
Market Value/New Car Price: \$\$88,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/60R18 Rear Tyre Size: 235/60R18
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		4,401.10	3,747.70	653.40	14.85
Miscellaneous Items		45.00	45.00	0.00	0.00
Labour		2,130.00	1,380.00	750.00	35.21
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
Gross To	otal (S\$)	6,576.10	5,172.70	1,403.40	21.34
+ GST 7.00/7.00	0% (S\$)	460.33	362.09	98.24	21.34
Nett Amou	unt (S\$)	7,036.43	5,534.79	1,501.64	21.34

INSPECTION

Date of Assignment: 15/11/2021 Present Location: Ricardo Auto Centre Pte Ltd (HQ)

Ricardo Auto Centre Pte Ltd (HQ)

Date Inspected: 17/11/2021 Inspected At: 160 Sin Ming Drive, #02-02, Sin Ming AutoCity

Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Mar 2022)

Parts: M1-SUV LEXUS RX270 2.7 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SFG9981B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty Par	t No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET (WCP)	Bent	550.00 F	*550.00 F
2	1		*BONNET SEAL (WCP)	Not Necessary	25.00 F	*-F
3	1		*RADIATOR GRILLE (WCP)	Broken	260.00 F	*260.00 F
4	1		*FRONT BUMPER (WCP)	Deformed	280.00 F	*280.00 F
5	1		*FRONT BUMPER SPONGE (WCP)	Cracked	60.00 F	*60.00 F
6	1		*FRONT BUMPER REINFORCEMENT (WCP)	Bent	220.00 F	*220.00 F
7	1		*FRONT BUMPER SIDE RETAINER RH & LH (WCP)	N/S Deformed	76.00 F	*40.00 F
8	1		*FRONT BUMPER NUMBER PLATE BRACKET (WCP)	Deformed	55.00 F	*55.00 F
9	10		*FRONT BUMPER CLIPS (WCP)	Necessary	15.00 F	*10.00 F
10	2		*HEADLAMP RH & LH (WCP)	Cracked	1,500.00 F	*1,500.00 F
11	1		*SEAL, HOOD TO RADIATOR GRILLE (WCP)	Not Necessary	25.00 F	*-F
12	10		*CLIPS, RADIATOR COVER (WCP)	Necessary	15.00 F	*12.00 F
13	1		*FRONT SUPPORT PANEL (WCP)	Repair	500.00 F	*-F
<u>Sup</u>	<u>plementar</u>	<u>y #1</u>				
14	1		*HEADLAMP ACTUATOR LH (WCP)	Broken	200.00 F	*200.00 F
15	1		*FRONT BUMPER LOWER GRILLE (WCP)	Broken	70.00 F	*70.00 F
<u>Sup</u>	<u>plementar</u>	<u>y #2</u>				
16	1		*HEADLAMP HID BULB LH (WCP)	Not Working	150.00 F	*150.00 F
F=Fra	nchise part.			Sub Total (S\$)	4,001.00	3,407.00
			+ Margin on L,N Items	• • •	400.10	340.70
				Total Parts (S\$)	4,401.10	3,747.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars		Repairer's	Amount
Mis	cellan	eous Items			
1	1	FRONT NUMBER PLATE W/HOLDER (BENT)		45.00	45.00
			Sub Total (S\$)	45.00	45.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO FOCUS HEADLAMP	New	30.00	30.00
2	TO SERVICE AIRCON, RECHARGE AIRCON GAS	New	100.00	100.00
3	TO CUT, WELD & STRAIGHTEN FRONT PORTION OF CAR CAUSED BY ACCIDENT, ADJUST & REPLACE DAMAGE PARTS.	New	900.00	500.00
4	TO SPRAY PAINT ON REPAIRED AREAS	New	1,100.00	750.00
	Gross Labou	r Cost (S\$)	2,130.00	1,380.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >