

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21011640/EUY3N2**Date:** 06/12/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00070682102

**Claimant Vehicle No :** GBB2205D **Insured Vehicle No :** YN5618R

Date of Loss: 06/11/2021 Nature of Claim: TP Claim No: SNM21D206403/C02/TOHHS

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **GBB2205D**

Make & Model: TOYOTA DYNA 100 MANUAL, 3.0 D (M) Engine No: 1KD1865757

Reg. Date: 22/09/2008 (Man. Year: 2008) Chassis No: JTFAT35Y50K200069

Colour: Silver Odometer: 594182 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 195R15 Rear Tyre Size: 195R15

Front Left Side: Dunlop 5 mm Rear Left Side: Dunlop 5 mm

Front Right Side: Dunlop 5 mm Rear Right Side: Dunlop 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,618.27	1,916.65	1,701.62	47.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,710.00	1,180.00	1,530.00	56.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>6,328.27</b>	<b>3,096.65</b>	<b>3,231.62</b>	<b>51.07</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>2,500.00</b>		
<b>(\$\$)</b>	6,328.27	2,500.00	3,828.27	60.49
<b>+ GST 7.00/7.00% (\$\$)</b>	442.98	175.00	267.98	60.49
<b>Nett Amount (\$\$)</b>	<b>6,771.25</b>	<b>2,675.00</b>	<b>4,096.25</b>	<b>60.49</b>

**INSPECTION**

Date of Assignment: 15/11/2021

Date Inspected: 19/11/2021 Inspected At: Kent Seng Car Service  
Blk 1017 Yishun Industrial Park A, #01-240  
Singapore 768759

Estimated Period of Repair: 4.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** Tan Hui Zhen

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 03 Dec 2021)	
<b>Parts:</b>	N/A	TOYOTA DYNA 100 MANUAL 3.0 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBB2205D)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,348.95 F	*1,348.95 FL
2	2		*TAILGATE LOCK (LEFT & RIGHT)	Not Necessary	361.20 F	*- FL
3	2		*TAILGATE HINGE	Bent	197.12 F	*197.12 FL
4	4		*TAILGATE BRACKET	Not Necessary	343.20 F	*- FL
5	4		*TAILGATE RUBBER MOUNTING	Not Necessary	168.00 F	*- FL
6	2		*TAIL LAMP (LEFT & RIGHT)	Cracked	462.80 F	*462.80 FL
7	2		*TAIL LAMP BRACKET (LEFT & RIGHT)	Repair	247.00 F	*- FL
8	1		*TAILGATE TOYOTA STICKER	Necessary	115.00 FS	*115.00 FS
9	1		*TAILGATE DYNA STICKER	Necessary	35.00 FS	*35.00 FS
10	1		*TAILGATE 70 KM STICKER	Necessary	10.00 FS	*10.00 FS
11	1		*TAILGATE 13 PAX STICKER	Necessary	10.00 FS	*10.00 FS
12	1		*REAR REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
13	1		*REAR NUMBER PLATE	Bent	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,618.27</b>	<b>2,418.87</b>
<b>- List Item Discount on L Items 0.00/25.00% (\$\$)</b>	0.00	502.22
<b>Total Parts (\$\$)</b>	<b>3,618.27</b>	<b>1,916.65</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	STRAIGHTENING,REPAIRING AND REALIGNING ONTO AFFECTED VEHICLE REAR PORTION,KNOCKING REAR END PANEL,DISMANTLE & REPLACE THE ABOVE MENTIONED PARTS	New	1,200.00	500.00
2	LABOUR FOR RESPRAY TAIL GATE (INNER & OUTER),TAIL GATE FOUR BRACKETS,TWO TAIL GATE HINGES & REAR END PANEL	New	1,100.00	400.00
3	TO SUPPLY TAIL GATE INNER ALUMINIUM CHECKER	New	350.00	250.00
4	TO CHECK WIRING	New	60.00	30.00
<b>Gross Labour Cost (\$)</b>			<b>2,710.00</b>	<b>1,180.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >