

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21011641/TGA3Q2**Date:** 17/08/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800015926
<b>Claimant Vehicle No :</b>	SHC7453U	<b>Insured Vehicle No :</b>	SLW6230A
Date of Loss:	15/11/2021	Nature of Claim:	TP
		Claim No:	4450152524SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHC7453U</b>		
Make & Model:	TOYOTA PRIUS, 1.8 (A)	Engine No:	2ZR2B88997
Reg. Date:	09/01/2019 (Man. Year: 2018)	Chassis No:	JTDKB3FU603078246
Colour:	Yellow	Odometer:	296609 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,427.10	1,427.10	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	820.00	630.00	190.00	23.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>2,247.10</b>	<b>2,057.10</b>	<b>190.00</b>	<b>8.46</b>
<b>+ GST 7.00/7.00% (S\$)</b>	157.30	144.00	13.30	8.46
<b>Nett Amount (S\$)</b>	<b>2,404.40</b>	<b>2,201.10</b>	<b>203.30</b>	<b>8.46</b>
<b>+ Loss of Use (2.0 x S\$50.00/day) (S\$)</b>		100.00		
<b>+ Car Rental (2.0 x S\$126.47/day) (S\$)</b>		252.94		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>2,556.04</b>		

INSPECTION

Date of Assignment:	15/11/2021	
Date Inspected:	15/11/2021	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days	

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	458.60 FL	*458.60 FL
2	1		*REAR BUMPER CENTER COVER -BLACK	Deformed	552.60 FL	*552.60 FL
3	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
4	1		*REAR BUMPER TOW COVER	Deformed	82.70 FL	*82.70 FL
5	1		*REAR BUMPER REINFORCEMENT	Bent	318.80 FL	*318.80 FL
6	1		*REAR FLOOR UNDER COVER	Deformed	220.50 FL	*220.50 FL
7	1		*REVERSE SENSOR	Not Working	135.70 FS	*135.70 FS
8	1		*REAR BUMPER MAT	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	1,840.90	1,840.90
- List Item Discount on L Items 25.00/25.00% (\$)	413.80	413.80
Total Parts (\$)	1,427.10	1,427.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	400.00	350.00
2	SPRAY PAINTING CHARGE	New	300.00	250.00
3	REMOVE/REFIX REVERSE SENSOR	New	120.00	30.00
<b>Gross Labour Cost (S\$)</b>			<b>820.00</b>	<b>630.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >