

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EGI21011647/DQF3N2**Date:** 04/05/2022REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : FBR5171M**Insured Vehicle No :** GBK6882A

Date of Loss: 13/11/2021

Nature of Claim:

TP

Claim No: CDMCG21002188

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **FBR5171M**

Make & Model: YAMAHA AEROX 155A, 155cc

Engine No: G3M1E050252

Reg. Date: 28/07/2020 (Man. Year: 2020)

Chassis No: MLESG584111050275

Colour: Black

Odometer: 0 km

Engine Capacity: 155 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/80R14

Rear Tyre Size: 140/70R14

Front Left Side: Pirelli 2 mm

Rear Left Side: Pirelli 2 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,443.50	1,557.00	886.50	36.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	370.00	200.00	170.00	45.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,813.50	1,757.00	1,056.50	37.55
Approved Total (Overridden) (S\$)		1,400.00		
Nett Amount (S\$)	2,813.50	1,400.00	1,413.50	50.24

INSPECTION

Date of Assignment: 15/11/2021

Date Inspected: 16/11/2021 Inspected At:

Sg 98 Motor Pte Ltd (HQ)

BLK 4001 ANG MO KIO INDUSTRIAL PARK 1

#01-21

Singapore 569622

Estimated Period of Repair: 3.0 days

Adjuster: BRYAN TANI**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 04 May 2022)	
Parts:	N/A	YAMAHA AEROX 155A 155cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBR5171M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR	Bent/Distorted	185.00 FL	*185.00 FL
2	1		*FRONT V PANEL	Mounting Cracked	190.00 FL	*190.00 FL
3	1		*FRONT LH HEAD SIDE PANEL	Mounting Broken	250.00 FL	*250.00 FL
4	1		*SIDE STAND	Cut	175.00 FL	*175.00 FL
5	1		*MAIN STAND	Repair	150.00 FL	*- FL
6	1		*SET HAND GUARD	N/s Damaged/O/s Not Necessary	250.00 FL	*125.00 FL
7	1		*FRONT MUDGUARD	Cut/Broken	195.00 FL	*195.00 FL
8	1		*HEAD LAMP	Mounting Broken	450.00 FL	*450.00 FL
9	1		*SIDE LAMP LH	Not Necessary	150.00 FL	*- FL
10	1		*SET FORK TUBE	Serviceable	560.00 FL	*- FL
11	1		*LH LOWER PANEL	Cut	160.00 FL	*160.00 FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (\$\$)	2,715.00 1,730.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	271.50 173.00
					Total Parts (\$\$)	2,443.50 1,557.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE & REPLACE ABOVE PARTS,ALIGN & ETC	New	250.00	120.00
2	REMOVE & REPLACE FORK TUBE	New	120.00	80.00
Gross Labour Cost (\$)			370.00	200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >