4/18/22, 1:17 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21011656/TEA3Q2

Date: 18/04/2022

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100407458-06

Claimant Vehicle SHB2989D Insured Vehicle No : SKL7494T

No:

Date of Loss: 12/11/2021 Nature of Claim: TP Claim No: 3545810290SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHB2989D

Make & Model: HYUNDAI AE IONIQ HEV, 1.6 DCT (A) Engine No: G4LEJU189546

Reg. Date: 30/04/2019 (Man. Year: 2018) Chassis No: KMHC851CVKU141097

Colour: Yellow Odometer: 518791 km

Engine Capacity: 1580 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm
Front Right Side: West Lake 6 mm
West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		2,140.76	796.12	1,344.64	62.81
Miscellaneous Items		0.00	0.00	0.00	
Labour		970.00	630.00	340.00	35.05
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	3,110.76	1,426.12	1,684.64	54.16
	+ GST 7.00/7.00% (S\$)	217.75	99.83	117.92	54.15
	Nett Amount (S\$)	3,328.51	1,525.95	1,802.56	54.16
	+ Loss of Use (1.5 x	S\$50.00/day) (S\$)	75.00		
	+ Car Rental (1.5 x S	\$128.40/day) (S\$)	192.60		
	+ Do	c/Search Fee (S\$)	2.00		
		Nett Liability (S\$)	1,795.55		
	Global Sui	m Settlement (S\$)	1,790.00		

INSPECTION

Date of Assignment: 15/11/2021

Date Inspected: ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive

Singapore 508969

Singapore

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER -RR BUMPER	Deformed	459.40 FL	*459.40 FL
2	1		*MOULDING ASSY -RR BUMPER C	Cut	451.25 FL	*451.25 FL
3	1		*PROTECTOR MAT	Necessary	50.00 FS	*50.00 FS
4	1		*BRACKET ASSY RR BUMPER SI	Not Necessary	55.80 FL	*- FL
5	1		*UNIT ASSY ,REAR CORNER RAD	Not Necessary	1,625.00 FL	*- FL
6	10		*BUMPER COVER CLIP REAR	Necessary	22.00 FL	*22.00 FL
F=Fra	nchise	part. S=SpcNet	t. L=ListItemDisc.			
				Sub Total (S\$)	2,663.45	982.65
			- List Item Discount or	L Items 20.00/20.00% (S\$)	522.69	186.53
				Total Parts (S\$)	2,140.76	796.12
			Report was unsubmitted	during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	400.00	350.00
2	SPRAYPAINT CHARGE	New	400.00	250.00
3	REMOVE/REFIX REVERSE SENSOR	New	50.00	30.00
4	DIAGNOSE AND RESET FUALT CODE	New	120.00	0.00
		Gross Labour Cost (S\$)	970.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >