Id	<	1	of 2 ?	>	Þ١	$\bigcirc$	<b>⊕</b>	100%	~		<sub>G</sub>	Find   Next	
----	---	---	--------	---	----	------------	----------	------	---	--	--------------	-------------	--



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	ale Des Experts En	Automob	pile								
	SOMPO INSURAN	ICE SINGAPORE PL		Ref:	CS3/SMO21011657/f3								
	50 RAFFLES PLAC SINGAPORE LANI	CE #03-03 D TOWERSINGAPORE 048623		Date:	16/11/2021								
				Code:	SMO								
1.	Policy Particulars :- (THIRD PARTY CLAIM)												
	Insured Veh.	SKX 1240K	Veh. Inspected	t	SCV 2053H								
	Policy No.		Coverage (\$)		0.00								
	Claim No.	CMTD2102127/GPL	Excess (\$)		0.00								
	Assign From	GRACE TEO	Assign Date		16/11/2021								
2.	•												
	Make & Model		c.c										
	Engine No.	HIDDEN	Year of Reg.										
	Chassis No.		Colour										
	Odometer	-	Steering										
	Brakes		Modification										
	General												
3.		Condition	ons of Tyres										
		Size	Make		Balance								
	R/H Front Tyre				mm								
	L/H Front Tyre				mm								
	R/H Rear Tyre				mm								
	L/H Rear Tyre				mm								
4.	Description of Damages												
5.	1		General Information										
	Accident Date	21/06/2021	Inspection Da	te	16/11/2021								
	Survey held at	HENG MOTOR SERVICES											
		NO. 91 DEFU LANE 10 #01-05A SWEE HIN BUILDING SINGAPORE 539221											
5a.	•	Remarks											
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.												