

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	NTUC INCOME IN	SURANCE CO-OPERATIVE LTD		Ref:	CS/INC21011658/Atf3e2	
	73 BRAS BASAH F #05-01 NTUC TRA 189556	ROAD DE UNION HOUSESINGAPORE		Date:	03/03/2022	
	ATTN: AZHARI AF	IDI		Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLD 4947D	Veh. Inspected	I	SMX 5093T	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1151019-002	Excess (\$)		0.00	
	Assign From	LIM CHAN HENG	Assign Date		16/11/2021	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA SHUTTLE	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2021	
	Chassis No.	GK82102427	Colour		BLACK	
	Odometer	28312 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	185/60 R15	YOKOHAMA		6 mm	
	L/H Front Tyre	185/60 R15	YOKOHAMA		6 mm	
	R/H Rear Tyre	185/60 R15	YOKOHAMA		6 mm	
	L/H Rear Tyre	185/60 R15	YOKOHAMA		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	11/11/2021	Inspect Date /	Time	16/11/2021 (11:12 AM)	
	Survey held at 8 KAKI BUKIT AVENUE 4 #08-45/46					
	Repairer SK AUTOMOBILE PTE LTD					
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days					