



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD
73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556
ATTN: JARED LIU YAO RONG

Ref: CS/INC21011659/Aqf3e2

Date: 01/03/2022

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKK 6141Z	Veh. Inspected	SKU 106M
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1151093-002	Excess (\$)	0.00
Assign From	LIM CHAN HENG	Assign Date	16/11/2021

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HARRIER	c.c	1986
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	ZSU600037263	Colour	BLACK
Odometer	104867 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/65 R17	YOKOHAMA	6 mm
L/H Front Tyre	225/65 R17	YOKOHAMA	6 mm
R/H Rear Tyre	225/65 R17	YOKOHAMA	6 mm
L/H Rear Tyre	225/65 R17	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	12/11/2021	Inspect Date / Time	16/11/2021 (11:24 AM)
Survey held at	8 KAKI BUKIT AVENUE 4 #08-46		
Repairer	SK AUTOMOBILE PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **2 Working Days**