



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2207789

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 19/12/2022
Reference CC3/CTI21011661/Rpa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SMK 5738K
Insured Veh. GBH 6145K
Claim No. SNM21D206702/C02
Policy No. DMCVSNA00025002100
Accident Date 13/11/2021
Inspection Date 18/11/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Ref: CC3/CTI21011661/Rpa3q2	
			Date: 19/12/2022	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBH 6145K	Veh. Inspected	SMK 5738K	
Policy No.	DMCVSNA00025002100	Coverage (\$)	0.00	
Claim No.	SNM21D206702/C02	Excess (\$)	0.00	
Assign From		Assign Date	18/11/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA LEXUS ES300H 4DR EXE	c.c	2487	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JTHB21B1202041232	Colour	BLUE	
Odometer	47703 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/45 R18	DUNLOP	6 mm	
L/H Front Tyre	235/45 R18	DUNLOP	6 mm	
R/H Rear Tyre	235/45 R18	DUNLOP	6 mm	
L/H Rear Tyre	235/45 R18	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/11/2021	Inspection Date	18/11/2021	
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMK 5738K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SUNDRIES (SN)	NECESSARY	100.00	50.00
1	COVER ,RR BUMPER (SN)	CRACKED	1,342.90	1,342.90
1	REINFORCEMENT ,RR (SN)	NOT NECESSARY	745.60	-
1	PROTECTOR ,RR (SN)	NOT NECESSARY	188.70	-
1	PROTECTOR ,RR (SN)	NOT NECESSARY	187.20	-
2	TAPE ,MOULDING ,NO.1 (SN)	NECESSARY	80.20	80.20
1	SUPPORT ,RR BUMPER (SN)	NOT NECESSARY	137.30	-
1	SUPPORT ,RR BUMPER (SN)	NOT NECESSARY	137.30	-
1	BRACKET ,RR BUMPER(SN)	NECESSARY	5.90	5.90
20	BUMPER CLIPS (SN)	NECESSARY	82.00	82.00
1	PAD ,RR BUMPER ,LH (SN)	NECESSARY	13.90	13.90
1	PAD ,RR BUMPER ,RH (SN)	NECESSARY	11.60	11.60
1	BUMPER SUB-ASSY ,RR (SN)	SCRATCHED	683.70	683.70
1	RETAINER ,RR BUMPER (SN)	NOT NECESSARY	167.10	-
1	BRACKET ,RR BUMPER LH (SN)	NECESSARY	5.90	5.90
1	SUPPORT ,RR BUMPER (SN)	NOT NECESSARY	86.60	-
1	SUPPORT ,RR BUMPER (SN)	NOT NECESSARY	79.10	-
1	PANEL SUB-ASSY ,BODY (SN)	NOT NECESSARY	844.70	-
1	PANEL SUB-ASSY (SN)	BENT	1,022.50	1,022.50
1	WEATHERSTRIP (SN)	NOT NECESSARY	254.30	-
1	CLOSER ASSY ,LUGGAGE (SN)	SCRATCHED	1,304.70	1,304.70
1	COVER ,LUGGAGE (SN)	NOT NECESSARY	96.20	-
1	COVER ,LUGGAGE (SN)	NOT NECESSARY	96.20	-
1	PLATE ,RR FLOOR (SN)	DEFORMED	363.90	363.90
1	PLATE ,LUGGAGE COMPT (SN)	NECESSARY	68.90	68.90
1	EMBLEM SYMBOL (SN)	NECESSARY	166.30	166.30
1	PLATE ,LUGGAGE COMPT (SN)	NECESSARY	80.60	80.60
1	COVER ,RR (SN)	NOT NECESSARY	38.00	-
1	COVER ,RR (SN)	NOT NECESSARY	38.00	-
1	RETAINER ,RR BUMPER (SN)	NOT NECESSARY	60.60	-
1	RETAINER ,RR BUMPER (SN)	NOT NECESSARY	60.60	-

Report Ref No. CC3/CTI21011661/Rpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	LAMP ASSY ,RR LH (SN)	NOT NECESSARY	1,070.10	-
1	LAMP ASSY ,RR RH (SN)	NOT NECESSARY	1,070.10	-
1	LAMP ASSY ,RR (SN)	NOT NECESSARY	1,377.50	-
1	LAMP ASSY ,RR (SN)	NOT NECESSARY	1,377.50	-
2	GUIDE RR (SN)	NECESSARY	7.00	7.00
4	CLIP ,ULTRASONIC (SN)	NECESSARY	49.20	49.20
4	SENSOR ,ULTRASONIC (SN)	NOT NECESSARY	1,963.20	-
1	REFLECTOR ASSY (SN)	NOT NECESSARY	49.30	-
1	REFLECTOR ASSY (SN)	NOT NECESSARY	49.30	-
1	PROTECTOR QUARTER (SN)	NOT NECESSARY	28.80	-
1	PROTECTOR QUARTER (SN)	NOT NECESSARY	28.80	-
1	GARNISH SUB-ASSY (SN) (ADDITIONAL)	DEFORMED	563.70	563.70
1	ANTENNA ELECTRICAL (SN) (ADDITIONAL)	CRACKED	72.60	72.60
			16,257.60	5,975.50
	LABOUR			
	TO REMOVE ALL NECESSARY PARTS TO ENABLE REPAIRING AND STRAIGHTEN ON REAR BUMPER ,REAR PANEL ,BOOT COVER AND FIX NEW PARTS.		4,330.00	2,598.00
	TO RESPRAY PAINT TO WHOLE REAR PORTION INCL REAR PANEL.		4,452.00	2,968.00
	TO REMOVE AND TRANSFER REAR BOOTS COMPONENT AND MECHANISM TO NEW BOOT .		433.00	433.00
	TO REMOVE AND TRANSFER BOOT SPOILER TO ENABLE REPAIR.		216.50	216.50
	TO REMOVE AND TRANSFER REAR REVERSE CAMERA TO NEW BOOT .		216.50	216.50
	SUPPLY BOOT SEALANT.		100.00	100.00
	SUPPLY REAR PANEL SEALANT .	NOT NECESSARY	100.00	-
	TO REMOVE AND REINSTALL REAR LUGGAGE TRIM ,GARNISH ETC TO ENABLE REPAIR.		433.00	433.00
	TO REMOVE AND TRANSFER REAR SENSOR TO NEW BUMPER ,REPLACE IF DAMAGE .		216.50	216.50
	TO CHECK WIRING AND LIGHTS FUNCTIONING AND CARRY OUT WATER LEAK TEST .		216.50	216.50

Report Ref No. CC3/CTI21011661/Rpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RESET ECU & REPROGRAMME .		216.50	216.50
			10,930.50	7,614.50
GRAND TOTAL			27,188.10	13,590.00
RECOMMENDED COST OF REPAIRS				13,590.00

Report Ref No. CC3/CTI21011661/Rpa3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMK 5738K

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMK 5738K

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

