

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG21011672/TQF3E2

Date: 29/07/2022

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100136932
Claimant Vehicle No :	SKU9877L	Insured Vehicle No :	SJQ6616B
Date of Loss:	13/11/2021	Nature of Claim:	TP
		Claim No:	2129897303SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU9877L	Engine No:	F1281154B38A12A
Make & Model:	MINI ONE, 1.2 5DR HB D/AB ABS DSC (A)	Chassis No:	WMWXS120302C73272
Reg. Date:	22/07/2015 (Man. Year: 2015)	Odometer:	144414 km
Colour:	Red		
Engine Capacity:	1198 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,764.06	6,579.03	12,185.03	64.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,740.00	1,590.00	2,150.00	57.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,504.06	8,169.03	14,335.03	63.70
Approved Total (Overridden) (S\$)		6,500.00		
(S\$)	22,504.06	6,500.00	16,004.06	71.12
+ GST 7.00/7.00% (S\$)	1,575.28	455.00	1,120.28	71.12
Nett Amount (S\$)	24,079.34	6,955.00	17,124.34	71.12

INSPECTION

Date of Assignment:	16/11/2021		
Date Inspected:	17/11/2021	Inspected At:	1 Kaki Bukit Ave 6 #01-08 Repairer: Tsl Auto Garage (HQ)
Estimated Period of Repair:	6.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (UPPER)	Deformed	1,251.80 FL	*850.00 FL
2	1		*REAR BUMPER (LOWER)	Deformed	874.40 FL	*425.00 FL
3	1		*REAR BUMPER LOWER COVER	Not Necessary	659.50 FL	*- FL
4	2		*REAR BUMPER RETAINER	Deformed	184.20 FL	*184.20 FL
5	2		*REAR BUMPER BRACKET	Deformed	126.80 FL	*126.80 FL
6	1		*REAR BUMPER TOW COVER	Deformed	68.60 FL	*68.60 FL
7	1		*REAR LEFT BUMPER INNER SIDE TRIM	Not Necessary	91.60 FL	*- FL
8	1		*REAR RIGHT BUMPER INNER SIDE TRIM	Not Necessary	91.60 FL	*- FL
9	1		*REAR LEFT BUMPER SIDE PROTECTOR	Not Necessary	160.60 FL	*- FL
10	1		*REAR RIGHT BUMPER SIDE PROTECTOR	Not Necessary	160.60 FL	*- FL
11	1		*REAR BUMPER REINFORCEMENT	Bent	520.80 FL	*520.80 FL
12	1		*REAR BUMPER CENTER SPONGE	Not Necessary	178.50 FL	*- FL
13	1		*REAR BUMPER CENTRE REFLECTOR	Cut	225.80 FL	*182.00 FL
14	1		*SET REAR BUMPER FOG LAMP GARNISH	Deformed	155.80 FL	*155.80 FL
15	1		*REAR TAILGATE ASSY	Bent	1,617.40 FL	*960.00 FL
16	1		*REAR TAILGATE CENTRE LOGO	Necessary	158.80 FL	*65.00 FL
17	1		*REAR TAILGATE ONE EMBLEM	Necessary	151.10 FL	*70.00 FL
18	1		*REAR TAILGATE COOPER EMBLEM	Necessary	160.10 FL	*75.00 FL
19	1		*REAR TAILGATE OUTER GARNISH	Not Necessary	277.80 FL	*- FL
20	2		*REAR TAILGATE NUMBER PLATE LAMPS	Not Necessary	128.80 FL	*- FL
21	1		*REAR TAILGATE INNER TRIM BOARD	Cracked	379.30 FL	*250.00 FL
22	1		*REAR TAILGATE LOCK	Bent	182.50 FL	*182.50 FL
23	1		*REAR TAILGATE LOCK CATCH	Not Necessary	68.20 FL	*- FL
24	2		*REAR TAILGATE HINGES	Not Necessary	185.80 FL	*- FL
25	1		*REAR TAILGATE WEATHERSTRIP	Cut	195.40 FL	*180.00 FL
26	1		*SET REAR TAILGATE RUBBER STOPPER	Not Necessary	68.80 FL	*- FL
27	2		*REAR TAILGATE DAMPERS	Not Necessary	585.80 FL	*- FL
28	1		*REAR LEFT TAILLAMP	Cracked	899.70 FL	*340.00 FL
29	1		*REAR RIGHT TAILLAMP	Cracked	899.70 FL	*340.00 FL
30	1		*REAR LEFT TAILLAMP PROTECTOR	Cut	156.60 FL	*105.00 FL
31	1		*REAR RIGHT TAILLAMP PROTECTOR	Cut	156.60 FL	*105.00 FL
32	1		*REAR LEFT TAILLAMP OUTER GARNISH	Not Necessary	123.10 FL	*- FL
33	1		*REAR RIGHT TAILLAMP OUTER GARNISH	Not Necessary	123.10 FL	*- FL
34	1		*REAR RIGHT FENDER	Not Necessary	1,022.50 FL	*- FL
35	1		*REAR LEFT FENDER PROTECTOR	Deformed	187.50 FL	*187.50 FL
36	1		*REAR RIGHT FENDER PROTECTOR	Deformed	187.50 FL	*187.50 FL
37	1		*REAR LEFT FENDER INNER SHIELD	Not Necessary	269.90 FL	*- FL
38	1		*REAR RIGHT FENDER INNER SHIELD	Not Necessary	269.90 FL	*- FL
39	1		*REAR LEFT FENDER INNER GARNISH	Not Necessary	396.30 FL	*- FL
40	1		*REAR RIGHT FENDER INNER GARNISH	Not Necessary	396.30 FL	*- FL
41	1		*REAR WIPER BLADE	Not Necessary	88.80 FL	*- FL
42	1		*REAR WIPER MOTOR	Not Necessary	253.40 FL	*- FL
43	2		*REAR AIR DUCT VENTILATOR	Deformed	180.10 FL	*180.10 FL
44	1		*REAR END LOWER PANEL	Bent	1,256.30 FL	*500.00 FL
45	1		*REAR END LOWER PANEL TOP GARNISH	Deformed	388.90 FL	*288.00 FL
46	1		*REAR EXHAUST MUFFLER ASSY	Repair	1,400.50 FL	*- FL
47	2		*REAR EXHAUST MUFFLER RUBBER MOUNTINGS	Not Necessary	68.80 FL	*- FL
48	1		*REAR EXHAUST MUFFLER HEAT SHIELD	Bent	179.90 FL	*179.90 FL
49	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	288.80 FL	*168.00 FL
50	1		*REAR RIGHT QUARTER GLASS MOULDING	Not Necessary	188.80 FL	*- FL
51	10		*REAR BUMPER CLIPS (UPPER)	Necessary	60.00 FS	*20.00 FS
52	10		*REAR BUMPER CLIPS (LOWER)	Necessary	60.00 FS	*20.00 FS
53	8		*REAR BUMPER LOWER COVER CLIPS	Not Necessary	40.00 FS	*- FS
54	4		*REAR LEFT BUMPER SIDE PROTECTOR CLIPS	Not Necessary	30.00 FS	*- FS
55	4		*REAR RIGHT BUMPER SIDE PROTECTOR CLIPS	Not Necessary	30.00 FS	*- FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	8		*REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	40.00 FS	*20.00 FS
57	4		*REAR TAILGATE OUTER GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
58	1		*REAR RIGHT FENDER SEALANT	Not Necessary	100.00 FS	*- FS
59	1		*REAR LEFT FENDER PROTECTOR CLIPS (6PCS)	Necessary	35.00 FS	*10.00 FS
60	1		*REAR RIGHT FENDER PROTECTOR CLIPS (6PCS)	Necessary	35.00 FS	*10.00 FS
61	6		*REAR LEFT FENDER INNER SHIELD CLIPS	Not Necessary	40.00 FS	*- FS
62	6		*REAR RIGHT FENDER INNER SHIELD CLIPS	Not Necessary	40.00 FS	*- FS
63	8		*REAR LEFT FENDER INNER GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
64	8		*REAR RIGHT FENDER INNER GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
65	1		*REAR END LOWER PANEL SEALANT	Necessary	140.00 FS	*40.00 FS
66	1		*REAR END LOWER PANEL TOP GARNISH CLIPS (6PCS)	Necessary	40.00 FS	*20.00 FS
67	4		*REAR BUMPER REVERSE SENSOR	Not Working	1,200.00 FS	*200.00 FS
68	1		*REAR NO PLATE WITH GARNISH	Not Necessary	100.00 FS	*- FS
69	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	100.00 FS	*50.00 FS
70	1		*REAR RIGHT QUARTER GLASS SEALANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	20,593.40	7,266.70
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,829.34	687.67
Total Parts (\$\$)	18,764.06	6,579.03

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN REAR AFFECTED AREA AND REPLACE REAR DAMAGED PARTS	New	1,400.00	600.00
2	TO PUTTY AND SPRAY PAINTING REAR PORTION	New	1,400.00	600.00
3	TO CHECK REAR LIGHTING AND WIRING	New	30.00	30.00
4	TO REMOVE AND INSTALL REAR TAILGATE LOCK MECHANISM	New	60.00	60.00
5	TO REMOVE AND INSTALL REAR EXHAUST MUFFLER ASSY	New	100.00	60.00
6	TO REMOVE AND INSTALL REAR FUEL TANK TO FACILITATE THE REPAIR	New	150.00	0.00
7	TO REMOVE AND INSTALL REAR INNER GARNISH AND TRIM TO FACILITATE THE REPAIR	New	140.00	60.00
8	TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA	New	120.00	30.00
9	TO REMOVE AND INSTALL REAR BUMPER REVERSE SENSOR	New	60.00	30.00
10	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE THE REPAIR	New	120.00	120.00
11	TO REMOVE AND INSTALL REAR RIGHT QUARTER GLASS	New	80.00	0.00
12	TOWING SERVICE	New	80.00	0.00
Gross Labour Cost (S\$)			3,740.00	1,590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >