

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21011680/EVF3N2**Date:** 01/12/2021**REFERENCE**

Insured/Claimant: CHUA TECK YONG,DANIEL (CAI DERONG,DANIEL) Policy No: 1900017303
Date of Loss: 16/11/2021 Nature of Claim: OD Claim No: 2459115250SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMJ1769C**
Make & Model: KIA CERATO, 1.6 (A) Engine No: G4FGJH702498
Reg. Date: 25/02/2019 (Man. Year: 2018) Chassis No: KNAF3416MK5009871
Colour: White Odometer: 56908 km
Engine Capacity: 1591 cc
Market Value/New Car Price: S\$70,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16
Front Left Side: Nexen 4 mm Rear Left Side: Nexen 4 mm
Front Right Side: Nexen 4 mm Rear Right Side: Nexen 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,638.80	1,198.00	1,440.80	54.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,340.00	900.00	440.00	32.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,978.80	2,098.00	1,880.80	47.27
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	3,678.80	1,798.00	1,880.80	51.13
+ GST 7.00/7.00% (S\$)	257.52	125.86	131.66	51.13
Nett Amount (S\$)	3,936.32	1,923.86	2,012.46	51.13

INSPECTION

Date of Assignment: 16/11/2021
Date Inspected: 17/11/2021 Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339
Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LAMP ASSY-HEAD,RH	Not Necessary	1,219.00 FL	*- FL
2	1		*ORNAMENT-KIA NO.115	Necessary	32.00 FL	*32.00 FL
3	1		*COVER-FR BUMPER	Dented	633.00 FL	*633.00 FL
4	1		*GRILLE-FRONT BUMPER	Cut	262.00 FL	*262.00 FL
5	1		*GRILLE ASSY-RADIATOR	Cut	328.00 FL	*328.00 FL
6	1		*GARNISH-RADIATOR GRILLE	Not Necessary	38.00 FL	*- FL
7	1		*MOULDING-FRONT BUMPER,RH	Cut	36.00 FL	*36.00 FL
8	1		*ABSORBER-FRONT BUMPER ENERGY	Broken	84.00 FL	*84.00 FL
9	1		*BRACKET-FR BUMPER UPR SIDE MTG	Not Necessary	22.00 FL	*- FL
10	1		*BEAM COMPLETE-FR BUMPER	Not Necessary	497.00 FL	*- FL
11	1		*SUNDRIES	Necessary	40.00 FS	*20.00 FS
12	1		*FRT NUMBER PLATE WITH FRAME	Broken	50.00 FS	*50.00 FS
13	1		*COVER-FR BUMPER FOG LAMP, RH (Supplementary)	Broken	15.00 FL	*15.00 FL
14	10		*CLIPS (Supplementary)	Necessary	20.00 FL	*20.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,276.00	1,480.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	637.20	282.00
Total Parts (\$\$)	2,638.80	1,198.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRT BUMPER PANEL,REINFORCEMENT & AFFECTED AREA	New	800.00	400.00
2	PAINT WORK ON FRT BUMPER PANEL	New	350.00	350.00
3	TO APPLY SEALANT ON AFFECTED AREA	New	40.00	0.00
4	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
Gross Labour Cost (\$\$)			1,340.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >