

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info				
AIG Asia Pacific Insurance Pte.	Cust No/Name	/Chua Teck Yong, Daniel (cai Der			
Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING	Reg No/Reg Date				
	Date In/Mileage	17/11/2021/ 0			
	Chassis No	KNAF3416MK5009871			
SINGAPORE 079120	Engine No	G4FGJH702498			
Contact No 64191000	Make/Model	KIA/CERATO 1.6 A EX G333			
	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK			

LAX00000	Credit	16/11/2021/	4						
		16/11/2021/		BLK	282 / Kevin Leon	g	42596		
F DNTOOOO		Description	of Goods	/ Services		Qty	Unit Price	Disc%	Amount
E PNT88000	FDT RIIMDE	D DANEL DET	NEODCEME	NT 0 AFFFO	TED 4054				800.0
E PNT98000	INI DUMPE	ER PANEL, REI	NFURCEME	NI & AFFEC	TED AREA				
PAINT WO	RK ON FRT	BUMPER PANE	:L						350.0
M SUNDRY									40.0
10 APPLY A 54900099	SEALANT	ON AFFECTED	AREA						
	RING & CH	ASSIS ELECTR	TCAL SVS	TEM					30.0
A 10028901		MOSIS ELECTR	TUNE 313	ICM					120.0
TO CARRY	OUT DIAG	NOSTIC CHECK	ON ELEC	TRONIC CON	TROL SYSTEM				120.0
M SUNDRY				- F]	П			50.0
M SUNDRY	Y FRI NUM	MBER PLATE WI	TH FRAME	2571	1000	157	\		
SUNDRIES				5)11	1111116		1		40.0
M LAMP ASS	Y-HEAD,RH					1.00	1219.00	20 00	075 2
M ORNAMENT	KIA NO.1	.15				1.00		20.00	975.2 25.6
M COVER-FR						1.00	633.00		506.4
M GRILLE-F						1.00	262.00		209.6
M GRILLE AS						1.00	328.00		262.4
M GARNISH-F						1.00		20.00	30.40
MOULDING-						1.00		20.00	28.80
		MPER ENERGY				1.00		20.00	67.20
		UPR SIDE MT	G			1.00		20.00	17.60
M BEAM COME	PLETE-FR	BUMPER				1.00	497.00	20.00	397.6
Confirm & a	ccepted by	/							
								·	D Meson or
						7% GST on	Net		3,950.8
						/% USI UN	3950.8	U	276.5
						To	tal Payabl	е	4,227.3
Authorized	signatory	and company s	tamn						

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.