

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21011681/ATY3N2**Date:** 20/12/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00098842101	
<b>Claimant Vehicle No :</b>	SMG973B	<b>Insured Vehicle No :</b>	SKK4793E	
Date of Loss:	06/11/2021	Nature of Claim:	TP	Claim No: SNM21D206427/C02/TANCHC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMG973B</b>		Engine No:	27191031207510
Make & Model:	MERCEDES-BENZ C180K, 1.6 (A)		Chassis No:	WDD2040452A275679
Reg. Date:	26/06/2009 (Man. Year: 2009)		Odometer:	191366 km
Colour:	Black			
Engine Capacity:	1597 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>			

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	225/40R18	Rear Tyre Size:	225/40R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,321.10	2,868.60	1,452.50	33.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,315.00	830.00	1,485.00	64.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>6,636.10</b>	<b>3,698.60</b>	<b>2,937.50</b>	<b>44.27</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>2,900.00</b>		
<b>(\$\$)</b>	6,636.10	2,900.00	3,736.10	56.30
<b>+ GST 7.00/7.00% (\$\$)</b>	464.53	203.00	261.53	56.30
<b>Nett Amount (\$\$)</b>	<b>7,100.63</b>	<b>3,103.00</b>	<b>3,997.63</b>	<b>56.30</b>

**INSPECTION**

Date of Assignment:	16/11/2021	SK Automobile Pte Ltd (HQ)
Date Inspected:	16/11/2021 Inspected At:	23 Kaki Bukit Avenue 4, #03-01 Vicom Inspection Centre
Estimated Period of Repair:	4.0 days	Singapore 415933

**Adjuster:** ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 18 Dec 2021)
<b>Parts:</b>	143	MERCEDES-BENZ C180K 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMG973B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP LH	Cut	1,100.00 FL	*1,100.00 FL
2	1		*FRONT HEADLAMP LOWER BRACKET LH	Bent	305.00 FL	*305.00 FL
3	1		*FRONT FENDER BLUE EFFICIENCY EMBLEM LH	Necessary	109.00 FL	*109.00 FL
4	1		*FRONT FENDER INNER SHIELD FRONT LH	Not Necessary	230.00 FL	*- FL
5	1		*FRONT FENDER INNER SHIELD REAR LH	Not Necessary	150.00 FL	*- FL
6	1		*FRONT BUMPER	Deformed	1,400.00 FL	*1,400.00 FL
7	2		*FRONT BUMPER CHROME MOLDING LH/RH	Necessary	240.00 FL	*240.00 FL
8	2		*FRONT BUMPER SIDE RETAINER LH/RH	Not Necessary	50.00 FL	*- FL
9	1		*FRONT BUMPER INNER SPONGE	Not Necessary	195.00 FL	*- FL
10	1		*FRONT FENDER INNER SHIELD CLIPS SET LH	Not Necessary	60.00 FS	*- FS
11	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
12	1		*SET FRONT BUMPER LED FOG LAMP	Not Necessary	780.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,699.00</b>	<b>3,184.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	377.90	315.40
<b>Total Parts (\$\$)</b>	<b>4,321.10</b>	<b>2,868.60</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	New	1,000.00	300.00
2	TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	New	750.00	500.00
3	TO APPLY ANTI-RUST & TUFF KOTE	New	95.00	0.00
4	TO PERFORM LIGHTING & WIRING CHECK	New	120.00	30.00
5	TO PERFORM DIAGNOSTIC CHECK & RESET MEMORY FAULT CODE TO IDENTIFICATION STANDARD	New	350.00	0.00
<b>Gross Labour Cost (\$)</b>			<b>2,315.00</b>	<b>830.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >