

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21011682/APA3Q2**Date:** 09/03/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070104487-01
Claimant Vehicle No :	SMQ1817K	Insured Vehicle No :	SMU300U
Date of Loss:	13/11/2021	Nature of Claim:	TP
		Claim No:	8705463421SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ1817K	Engine No:	L15B6020424
Make & Model:	HONDA SHUTTLE, 1.5 (A)	Chassis No:	GK82100345
Reg. Date:	31/10/2019 (Man. Year: 2019)	Odometer:	25631 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,746.56	4,664.08	5,082.48	52.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,180.00	1,460.00	720.00	33.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,926.56	6,124.08	5,802.48	48.65
Approved Total (Overridden) (S\$)		4,900.00		
(S\$)	11,926.56	4,900.00	7,026.56	58.92
+ GST 7.00/7.00% (S\$)	834.86	343.00	491.86	58.92
Nett Amount (S\$)	12,761.42	5,243.00	7,518.42	58.92
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
(S\$)		5,603.00		
Liabe Amount (80.00%) (S\$)		4,482.40		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,484.40		
Global Sum Settlement (S\$)		4,400.00		

INSPECTION

Date of Assignment:	16/11/2021	New Hock Teck Motor Pte Ltd (HQ)
Date Inspected:	16/11/2021 Inspected At:	1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit
Estimated Period of Repair:	5.0 days	Singapore 417883

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,100.90 FL	*1,100.90 FL
2	1		*FRONT BUMPER REINFORCEMENT	Dented	297.30 FL	*297.30 FL
3	2		*FRONT BUMPER SIDE RETAINER	Damaged	30.60 FL	*30.60 FL
4	1		*FRONT BUMPER FOG LAMP COVER	O/S Cracked	310.40 FL	*155.20 FL
5	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	158.10 FL	*- FL
6	1		*FRONT BUMPER LOWER PANEL	Repair	312.40 FL	*- FL
7	2		*FRONT HEADLAMP	Cracked	2,031.20 FL	*2,031.20 FL
8	1		*FRONT HEADLAMP LOWER BRACKET	O/S Cracked	76.80 FL	*38.40 FL
9	1		*FRONT GRILLE	Not Necessary	883.90 FL	*- FL
10	1		*FRONT GRILLE BASE	Cracked	436.50 FL	*436.50 FL
11	1		*FRONT GRILLE LOGO	Not Necessary	320.10 FL	*- FL
12	2		*FRONT FENDER	Repair	1,035.20 FL	*- FL
13	2		*FRONT FENDER INNER SHIELD	Torn	221.00 FL	*221.00 FL
14	1		*FRONT FENDER INNER PANEL RH	Dented	894.70 FL	*395.00 FL
15	1		*FRONT FENDER INNER EXTENSION PANEL RH	Buckled	178.50 FL	*178.50 FL
16	1		*WIPER WASHER TANK	Deformed	412.30 FL	*258.00 FL
17	1		*FRONT SUPPORT PANEL	Not Necessary	760.40 FL	*- FL
18	1		*AIR CON CONDENSER	Not Necessary	985.40 FL	*- FL
19	1		*FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
20	1		*FRONT BUMPER UNDER COVER CLIPS	Not Necessary	60.00 FS	*- FS
21	1		*FRONT GRILLE CLIPS	Necessary	60.00 FS	*20.00 FS
22	1		*AIR CON GAS	Not Necessary	100.00 FS	*- FS
23	1		*FRONT NUMBER PLATE WITH NUMBER PLATE	Not Necessary	60.00 FS	*- FS
24	1		*FRONT TYRE RH	Not Necessary	280.00 FS	*- FS
25	1		*FRONT RIM RH	Cut	750.00 FS	*500.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$\$)	11,835.705,692.60
					- List Item Discount on L Items 20.00/20.00% (\$\$)	2,089.141,028.52
					Total Parts (\$\$)	9,746.564,664.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING	New	1,000.00	650.00
2	LABOUR FOR SPRAYPAINTING	New	800.00	700.00
3	LABOUR FOR REMOVE & RENEW AIR CON CONDENSER ,TOP UP & VACUUM AIR CON GAS	New	150.00	0.00
4	WIRING CHECK	New	80.00	30.00
5	TO APPLY RUST PROOF /TUFF COAT ON ACCIDENT AREAS	New	150.00	80.00
Gross Labour Cost (\$\$)			2,180.00	1,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >