

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21011687/GVY3E2

Date: 26/11/2021

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMHCSNA00012722101

Claimant Vehicle
No : SG6018Z

Insured Vehicle
No : SMU7032Y

Date of Loss: 05/11/2021

Nature of Claim: TP

Claim
No: SNM21D206582/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SG6018Z**

Make & Model: MAN A95, 10.5 D (A)

Engine No: 50351460635145

Reg. Date: 03/12/2018 (Man. Year: 2018)

Chassis No: WMAA95ZZXKF008277

Colour: Multi-colour

Odometer: 261941 km

Engine Capacity: 10518 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5

Rear Tyre Size: 275/70 R22.5 (D)

Front Left Side: Firenza 6 mm

Rear Left Side: Firenza 6/6 mm

Front Right Side: Firenza 6 mm

Rear Right Side: Firenza 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,200.00	1,200.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,240.00	2,590.00	650.00	20.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,440.00	3,790.00	650.00	14.64
+ GST 7.00/7.00% (S\$)	310.80	265.30	45.50	14.64
Nett Amount (S\$)	4,750.80	4,055.30	695.50	14.64

INSPECTION

Date of Assignment: 18/11/2021

Date Inspected: 17/11/2021 Inspected At:

310 Mandai Rd Singapore 779404

Repairer: Tower Transit Singapore Pte Ltd

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 26 Nov 2021)	
Parts:	N/A	MAN A95 10.5 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SG6018Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BATTERY DOOR PANEL	Cracked	440.00 F	*440.00 F
2	1		*BATTERY DOOR FRAME	Necessary	580.00 F	*580.00 F
3	1		*NS REAR SERVICE DOOR LOCK	Damaged	140.00 F	*140.00 F
4	1		*BATTERY BOX STICKER	Necessary	40.00 F	*40.00 F
F=Franchise part.						
					Total Parts (S\$)	1,200.00
						1,200.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE : - ITEM NOS 1 - 4	New	2,600.00	1,950.00
2	SPRAY PAINTING : - BATTERY DOOR PANEL	New	640.00	640.00
Gross Labour Cost (S\$)			3,240.00	2,590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >