

ASSIGNMENT

From:

Date:

Estimated Cost:

OD ☒ TP ☒ / N/S / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s TOWER TRANSIT(MANDAI DEPOT)

of

Insured: SMU 7032Y

Policy No. DMHCSNA00012722101

Claims No. SNM21D206582/C02/LEEPG

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SG6018Z

Yr Regn: 03 Dec/2018

Type: M.Car / M.Cycle / ☒ Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MAN A95 c.c. 10518

Colour: Multicolor A/C: Insured / Std / NI / NA

Sp. Reading: 261941.0 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WMAA95ZZXKF008277 *

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Jammed / Leaked / Burnt orBrake: ☒ Jammed / Leaked / Burnt orModi: ☒ Nil / Rim / STD A/Rim or

Tyre Size: F: 275/70R22.5

R: 275/70R22.5

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FIRENZA

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 5/11/21 D.O.I. 17-11-2021

Survey held at W/S 11AM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S FRONT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

25/11/21 Final fig \$3790 confirmed by email (Red 2960.80, 43%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 25/11/21-typist

Report Filed: Merimen

Long Cond / LPIB: IBI: \$3790

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Insp (\$)☐ : A/Sel end (\$)

Survey Fee:

Transportation:

\$ + RS. SI

Photos

Other:

TOTAL