

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21011690/KTY3Q2**Date:** 21/04/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00118352000		
Claimant Vehicle No :	YP7473S	Insured Vehicle No :	XE5385X		
Date of Loss:	13/11/2021	Nature of Claim:	TP	Claim No:	SNM21D206560/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP7473S		Engine No:	N04CUS35016
Make & Model:	HINO XZU405R, 4.0 D (M)		Chassis No:	JHHUCS3H00K022989
Reg. Date:	26/10/2017 (Man. Year: 2017)		Odometer:	109800 km
Colour:	Blue			
Engine Capacity:	4009 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/85 R16	Rear Tyre Size:	195/85 R16 (D)
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Bridgestone 9/9 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Bridgestone 9/9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,056.00	15,431.00	2,625.00	14.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	28,560.00	15,930.00	12,630.00	44.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	46,616.00	31,361.00	15,255.00	32.72
Approved Total (Overridden) (S\$)		24,850.00		
(S\$)	46,616.00	24,850.00	21,766.00	46.69
+ GST 7.00/7.00% (S\$)	3,263.12	1,739.50	1,523.62	46.69
Nett Amount (S\$)	49,879.12	26,589.50	23,289.62	46.69

INSPECTION

Date of Assignment:	16/11/2021	
Date Inspected:	16/11/2021	Inspected At: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	24.0 days	

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source:	(Last Synchronised: 21 Apr 2022)	
Parts:	N/A	HINO XZU405R 4.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP7473S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*CABIN REAR PANEL	Bent	900.00 F	*900.00 F
2	1		*CABIN REAR PANEL LOWER INNER BEAM	Bent	180.00 F	*180.00 F
3	2		*CABIN REAR PANEL INNER SIDE PANELS	Bent	120.00 F	*120.00 F
4	1		*REAR WINDSCREEN GLASS RUBBER	Necessary	80.00 F	*80.00 F
5	1		*FRONT WINDSCREEN GLASS MOULDING	Necessary	145.00 F	*145.00 F
6	1		*TOP ROOF PANEL	Bent	480.00 F	*480.00 F
7	1		*TOP ROOF PANEL INNER BEAM 1	Bent	70.00 F	*70.00 F
8	1		*TOP ROOF PANEL INNER BEAM 2	Bent	120.00 F	*120.00 F
9	1		*TOP ROOF LINING	Distorted	1,100.00 F	*1,100.00 F
10	1		*METER OUTER COVER	Cut	140.00 F	*140.00 F
11	1		*CABIN REAR LH PILLAR OUTER	Bent	490.00 F	*490.00 F
12	1		*CABIN REAR LH PILLAR INNER	Bent	100.00 F	*100.00 F
13	1		*CABIN REAR LH PILLAR TOP INNER	Bent	290.00 F	*290.00 F
14	1		*FRT LH WHEEL ARP TOP GARNISH	Buckled	105.00 F	*105.00 F
15	1		*CABIN REAR LH LOCK	Bent / Jammed	400.00 F	*400.00 F
16	1		*CABIN REAR LH LOCK LATE	Distorted	120.00 F	*120.00 F
17	1		*CABIN REAR LH LOCK SENSOR	Missing	250.00 F	*250.00 F
18	1		*CABIN REAR LH INNER GARNISH	Distorted	298.00 F	*298.00 F
19	1		*TAILLAMPS	N/S Cracked	200.00 F	*100.00 F
20	1		*AIR FILTER HOUSING	Dented	395.00 F	*395.00 F
21	1		*STICKER -7 PAX	Necessary	10.00 FS	*10.00 FS
22	1		*STICKER -60KM/H	Necessary	10.00 FS	*10.00 FS
23	1		*REAR LH MUD GUARD	Distorted / Cut	220.00 FS	*220.00 FS
24	1		*REAR NUMBER PLATE	Bent	18.00 FS	*18.00 FS
25	1		*REAR SAFETY BAR	Bent	480.00 FS	*480.00 FS
26	1		*REAR LH TYRE (70%)	Cut	350.00 FS	*245.00 FS
27	1		*FRONT WINDSCREEN GLASS GUM	Necessary	80.00 FS	*40.00 FS
28	2		*REAR MAIN WOODEN CHASSIS	Cracked	900.00 FS	*900.00 FS
29	1		*REAR STEP WOODEN BAR	Cracked	120.00 FS	*120.00 FS
30	1		*REAR CROSS WOODEN MEMBER	Cracked	2,800.00 FS	*2,000.00 FS
31	1		*REAR WOODEN BOARD	Cracked	3,500.00 FS	*2,900.00 FS
32	1		*FRONT LH DOOR	Repair	980.00 F	*- F
33	1		*FRONT LH DOOR INNER RUBBER	Cut	100.00 F	*100.00 F
34	1		*FRONT LH DOOR INNER LOCK	Dented	210.00 F	*210.00 F
35	1		*DRIVER INJECTION	Dented	950.00 F	*950.00 F
36	1		*STEERING RELAY TILT CAB CONTROL	Bent	480.00 F	*480.00 F
37	1		*CABIN REAR CROSSBAR BRIDGE	Distorted / Bent	690.00 F	*690.00 F
38	1		*CABIN REAR LH PANEL INNER	Bent	175.00 F	*175.00 F

F=Franchise part. S=SpcNett.

Total Parts (S\$)	18,056.00	15,431.00
--------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING (BY OWNER)	New	100.00	100.00
2	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	60.00	60.00
3	REMOVE & REFIX TOP ROOF LINING ,SEAT ,CARPET ,GARNISH ,ETC	New	100.00	100.00
4	REMOVE AND REFIX FRONT WINDSCREEN GLASS	New	150.00	120.00
5	REMOVE & REFIX CABIN FRT BUMPER ASSY ,KNOCK & REPAIR FRT RH DOOR ,TO STRAIGHTEN CABIN STRUCTURE ,CUT,WELD & RENEW CABIN REAR PANEL ,REAR PANEL INNER BEAM & SIDE BEAM ,CABIN REAR LH PILLAR ,TO BE CONTINUED	New	3,200.00	2,800.00
6	TO CUT ,WELD & RENEW CABIN TOP ROOF PANEL & INNER BEAM ,KNOCK & REPAIR FRT LH WHEEL PANEL ,CABIN REAR FLOOR BOARD PANEL ,REMOVE & REFIX CABIN ASSY ,REALIGN STRUCTURE & CABIN POSITION (NPA)	New	0.00	0.00
7	PUTTY & RESPRAY ON CABIN TOP ROOF PANEL ,REAR PANEL ,REAR LH PILLAR ,LH WHEEL ARP PANEL ,FLOOR BOARD PANEL,FRT BUMPER ,FRT LH DOOR & ALL AFFECTED AREAS	New	1,500.00	1,300.00
8	REMOVE & REFIX DASHBOARD ,GARNISH ,METER & CHECK WIRING	New	250.00	250.00
9	PUTTY & RESPRAY ON REAR CANOPY	New	1,500.00	1,350.00
10	TO REWRITE ADVERTISEMENT	New	1,300.00	1,150.00
11	TO REMOVE ALUMINIUM BOX :TO REPLACE WOODEN PLATFORM PLANK AND WOODEN CROSS MEMBER	New	4,500.00	0.00
12	TO REMOVE ALUMINIUM BOX DAMAGE PARTS & ATTACHMENT ,WELD AND STRAIGHTEN ALUMINIUM STRUCTURE ,REPLACE ALUMINIUM PANEL ALIGN IN BOX IN POSITION	New	6,200.00	0.00
13	TO REMOVE ALL THE DAMAGED WOODEN PLATFORM AND REBUILD REAR WOODEN TRUCK INCLUDING SUPPLY ALL NECESSARY MATERIAL	New	1,800.00	1,600.00
14	TO SUPPLY ALL NECESSARY MATERIAL FOR REBUILD REAR ALUMINIUM BOX ,LABOUR TO REMOVE REAR ALUMINIUM BOX ,ALL DAMAGED PART & RE-STRAIGHTEN ALUMINIUM STRUCTURE BOX AND CHECK LEAKING	New	7,500.00	6,800.00
15	TO REMOVE AND REFIT DRIVER INJECTION STEERING RELAY TILT CAB CONTROL AND RESET SYSTEM	New	200.00	150.00
16	TO REMOVE AND REFIT CABIN REAR CROSS BAR BRIDGE AND REALIGN THE SAME	New	200.00	150.00
Gross Labour Cost (\$\$)			28,560.00	15,930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >