

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21011691/GEA3Q2**Date:** 20/04/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : SMX8751H **Insured Vehicle No :** SLS8096D
 Date of Loss: 14/11/2021 Nature of Claim: TP Claim No: MFL2021D0004927

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMX8751H**
 Make & Model: HONDA CIVIC, 1.6 VTI CVT (A) Engine No: R16B25520616
 Reg. Date: 03/02/2021 (Man. Year: 2020) Chassis No: MRHFC5650LT000489
 Colour: Grey Odometer: 8354 km
 Engine Capacity: 1597 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R16 Rear Tyre Size: 215/55 R16
 Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm
 Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,601.56	1,911.57	689.99	26.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,330.00	7,280.00	2,050.00	21.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,931.56	9,191.57	2,739.99	22.96
+ GST 7.00/7.00% (S\$)	835.21	643.41	191.80	22.96
Nett Amount (S\$)	12,766.77	9,834.98	2,931.79	22.96
+ Loss of Use (8.0 x S\$60.00/day) (S\$)		480.00		
Nett Liability (S\$)		10,314.98		

INSPECTION

Date of Assignment: 16/11/2021
 Date Inspected: 22/11/2021 Inspected At: Kah Motor Co Sdn Bhd (Ubi)
 Estimated Period of Repair: 7.0 days 15 Ubi Road 4
 Singapore 408610

Adjuster: XING GUO QIANG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Apr 2022)
Parts:	143	HONDA CIVIC 1.6 VTI CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMX8751H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACE ASSY,RR.BUMPER	Deformed	462.90 FS	*462.90 FS
2	1		*GARNISH ASSY ,RR.BUMPER LOWER	Not Necessary	96.37 FS	*- FS
3	1		*BEAM COMPRR.BUMPER	Bent	141.00 FS	*141.00 FS
4	1		*BRACKETL.RR.BUMPER SIDE	Deformed	1.95 FS	*1.95 FS
5	1		*GARNISH,L.RR.BUMPER SIDE	Not Necessary	6.67 FS	*- FS
6	1		*REFLECTOR ASSYL.RR	Not Necessary	6.15 FS	*- FS
7	1		*SPACERR.RR.BUMPER SIDE	Necessary	8.62 FS	*8.62 FS
8	1		*SPACERL.RR.BUMPER SIDE	Necessary	8.62 FS	*8.62 FS
9	1		*CLIP BUMPER (7 PCS)	Necessary	12.07 FS	*12.07 FS
10	1		*PANEL SETRR	Buckled	208.12 FS	*208.12 FS
11	1		*STIFFENER ,R.RR.PANEL SIDE	Necessary	22.87 FS	*22.87 FS
12	1		*STIFFENERL ,R.RR.PANEL SIDE	Necessary	22.87 FS	*22.87 FS
13	1		*LINING ASSYRR.PANEL	Deformed	37.72 FS	*37.72 FS
14	1		*LID COMP TRUNK	Buckled	416.17 FS	*416.17 FS
15	1		*GARNISH ASSYRR.LICENSE	Deformed	86.10 FS	*86.10 FS
16	1		*EMBLEM,H -MARK	Necessary	10.50 FS	*10.50 FS
17	1		*NUT PLUSH 3MM (2 PCS)	Necessary	3.15 FS	*3.15 FS
18	1		*LOCK ASSYTRUNK	Bent	63.67 FS	*63.67 FS
19	1		*LIGHT ASSYL.LID	Not Necessary	104.70 FS	*- FS
20	1		*TAILLIGHT ASSYL	Cracked	240.82 FS	*240.82 FS
21	1		*ANTENNA ASSYL.F	Not Necessary	47.40 FS	*- FS
22	1		*BUZZER ASSYSMART	Not Necessary	49.05 FS	*- FS
23	3		*SENSOR ASSY ,PARKING	Not Necessary	349.65 FS	*- FS
24	1		*EMBLEM SETRR	Necessary	10.05 FS	*10.05 FS
25	1		*EMBLEMRR	Necessary	9.37 FS	*9.37 FS
26	1		*NUMBER PLATE WITH CASING-OPC-L	Necessary	45.00 FS	*45.00 FS
27	1		*SEAL NUMBER PLATE	Necessary	80.00 FS	*80.00 FS
28	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	2,601.56	1,911.57
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	INSPECT RR LIGHTING MECHANISMS PERFORM WATER	New	180.00	150.00
2	BODY JOINT SEALANT	New	100.00	100.00
3	BODY UNDERSIDE COATING	New	100.00	100.00
4	APPLY BODY UNDERSIDE COATING	New	250.00	180.00
5	REMOVE & INSTALL REVERSE SENSORS	New	200.00	150.00
6	REMOVE & INSTALL & CALIBRATE REAR VIEW CAMERA	New	450.00	350.00
7	RESET VEHICLE SMART ENTRY SYSTEM	New	450.00	350.00
8	REMOVE & TRANSFER ITEMS TO NEW TRUNK LID	New	450.00	350.00
9	REMOVE & INSTALL REAR COMPARTMENT LININGS	New	450.00	350.00
10	CUT OFF & RENEW RR PANEL STRAIGHTEN ALIGN	New	3,300.00	2,600.00
11	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	3,400.00	2,600.00
Gross Labour Cost (\$\$)			9,330.00	7,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >