

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI21011693/DTY3E2

**Date:** 04/05/2022

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00121502000  
**Claimant Vehicle No :** SNB6933S **Insured Vehicle No :** GBJ814S  
Date of Loss: 15/11/2021 Nature of Claim: TP Claim No: SNM21D206580/C2/IRENE

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNB6933S**  
Make & Model: TOYOTA WISH, 1.8 CVT (A) Engine No: 2ZR1412207  
Reg. Date: 25/08/2014 (Man. Year: 2014) Chassis No: JTDGG20W50J001424  
Colour: Gold Odometer: 78682 km  
Engine Capacity: 1798 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

### CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15  
Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm  
Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	33,298.72	8,246.17	25,052.55	75.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,070.00	2,700.00	8,370.00	75.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>44,368.72</b>	<b>10,946.17</b>	<b>33,422.55</b>	<b>75.33</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>8,700.00</b>		
<b>Nett Amount (S\$)</b>	<b>44,368.72</b>	<b>8,700.00</b>	<b>35,668.72</b>	<b>80.39</b>

### INSPECTION

Date of Assignment: 16/11/2021  
Date Inspected: 17/11/2021 Inspected At: CS Ong Auto Pte Ltd (HQ)  
BLK 10 ANG MO KIO IND PARK 2A #02-16 AMK  
AUTO POINT  
Singapore 568047  
Estimated Period of Repair: 7.0 days

**Adjuster:** BRYAN TANI

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 04 May 2022)
<b>Parts:</b> M1-MPV	TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SNB6933S)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Necessary	1,765.10 FL	*- FL
2	1		*BONNET LOGO	Not Necessary	86.92 FL	*- FL
3	1		*BONNET INSULATOR	Not Necessary	312.75 FL	*- FL
4	2		*BONNET HINGE LH/RH	Not Necessary	135.48 FL	*- FL
5	1		*BONNET LOCK	Not Necessary	376.65 FL	*- FL
6	1		*BONNET SEAL	Not Necessary	136.54 FL	*- FL
7	1		*HEAD LAMP LH /RH	N/S MtgCracked/O/SNotNecessary	3,382.14 FL	*1,225.10 FL
8	2		*HEAD LAMP LOWER BRACKET LH/RH	Not Necessary	396.00 FL	*- FL
9	1		*FRONT GRILLE	Mtg Cracked	601.90 FL	*419.30 FL
10	1		*FRONT GRILLE CHROME	Not Necessary	781.20 FL	*- FL
11	1		*FRONT BUMPER	Distorted / Mtg Cracked	1,081.70 FL	*692.00 FL
12	2		*FRONT BUMPER SIDE RETAINER LH/RH	Not Necessary	167.20 FL	*- FL
13	2		*FRONT BUMPER FOG LAMP LH/RH	Not Necessary	742.80 FL	*- FL
14	2		*FRONT BUMPER FOG LAMP GARNISH LH/RH	Not Necessary	598.20 FL	*- FL
15	2		*FRONT BUMPER FOG LAMP CHROME LH/RH	Not Necessary	574.20 FL	*- FL
16	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	439.80 FL	*- FL
17	1		*FRONT BUMPER UNDER COVER	Not Necessary	499.10 FL	*- FL
18	1		*FRONT BUMPER SPONGE	Torn	295.97 FL	*131.00 FL
19	1		*FRONT REINFORCEMENT BAR	Not Necessary	1,075.48 FL	*- FL
20	1		*FRONT SUPPORT PANEL	Not Necessary	1,648.92 FL	*- FL
21	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	315.78 FL	*- FL
22	1		*FRONT BRACE PANEL	Not Necessary	84.63 FL	*- FL
23	2		*FRONT FENDER LH/RH	Not Necessary	1,650.80 FL	*- FL
24	2		*FRONT FENDER INNER SHIELD LH/RH	Not Necessary	380.20 FL	*- FL
25	1		*TAILGATE	Buckled	1,610.10 FL	*1,272.00 FL
26	1		*TAILGATE WINDSCREEN MOULDING	Necessary	192.70 FL	*192.70 FL
27	1		*TAILGATE LOGO	Necessary	80.20 FL	*51.10 FL
28	1		*TAILGATE CENTER CHROME MOULDING	Cracked	439.10 FL	*309.70 FL
29	2		*TAILGATE NO PLATE LAMP LH/RH	Not Necessary	184.20 FL	*- FL
30	1		*TAILGATE LOCK	Damaged	343.50 FL	*343.50 FL
31	1		*TAILGATE SWITCH	Not Necessary	188.55 FL	*- FL
32	1		*TAILGATE WEATHER STRIP	Deformed / Necessary	304.00 FL	*304.00 FL
33	1		*SET TAILGATE STOPPERS	Serviceable	36.40 FL	*- FL
34	1		*TAILGATE INNER TRIM BOARD	Mtg Cracked	928.20 FL	*485.00 FL
35	2		*TAILGATE LAMP LH/RH	O/S Cracked / N/S Cut	796.20 FL	*796.20 FL
36	1		*TAILGATE WIPER MOTOR	Not Necessary	672.00 FL	*- FL
37	1		*TAILGATE WIPER ARM	Not Necessary	198.20 FL	*- FL
38	2		*TAILGATE DAMPER LH/RH	Not Necessary	898.00 FL	*- FL
39	2		*TAILGATE HINGE LH/RH	Not Necessary	182.40 FL	*- FL
40	1		*TAILGATE VALVEMATIC EMBLEM	Necessary	110.20 FL	*84.70 FL
41	1		*TAILGATE ELEGANCE EMBLEM	Necessary	112.90 FL	*59.30 FL
42	2		*TAIL LAMP LH /RH	Mtg Cracked	1,345.20 FL	*1,193.60 FL
43	2		*TAIL LAMP PANEL LH/RH	Not Necessary	713.46 FL	*- FL
44	1		*REAR BUMPER	Broken	830.50 FL	*625.50 FL

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	2		*REAR BUMPER SIDE RETAINER LH/RH	Serviceable	179.00 FL	*- FL
46	2		*REAR BUMPER REFLECTOR LH/RH	Not Necessary	193.80 FL	*- FL
47	2		*REAR BUMPER BRACKET LH/RH	Not Necessary	284.00 FL	*- FL
48	1		*REAR END PANEL	Dented	1,090.60 FL	*540.80 FL
49	1		*REAR END PANEL TOP GARNISH	Mtg Deformed	332.96 FL	*253.20 FL
50	1		*REAR FLOOR PANEL EXTENSION	Not Necessary	1,743.10 FL	*- FL
51	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	562.90 FL	*- FL
52	1		*REAR FLOOR PANEL TOOL BOX	Not Necessary	350.27 FL	*- FL
53	2		*REAR FLOOR QUARTER PANEL LH/RH	Not Necessary	647.80 FL	*- FL
54	2		*REAR FENDER LH/RH	Repair	3,077.18 FL	*- FL
55	2		*REAR FENDER QUARTER GLASS MOULDING LH/RH	Not Necessary	858.40 FL	*- FL
56	2		*REAR FENDER INNER TRIM BOARD LH/RH	Cracked	1,757.74 FL	*1,159.60 FL
57	1		*REAR EXHAUST PIPE	Not Necessary	1,198.87 FL	*- FL
58	1		*REAR EXHAUST MOUNTING	Not Necessary	81.50 FL	*- FL
59	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	125.63 FL	*- FL
60	1		*SPARE TYRE BOLT	Not Necessary	297.28 FL	*- FL
61	1		*SPARE TYRE HOLDER	Not Necessary	315.00 FL	*- FL
62	1		*SPARE TYRE BRACKET	Not Necessary	229.00 FL	*- FL
63	1		*TAILGATE INNER HANDLE	Deformed	98.10 FL	*98.10 FL
64	1		*REAR KEYLESS SENSOR	Mtg Broken	399.70 FL	*138.50 FL
65	1		*BONNET INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
66	1		*FRONT GRILLE CLIPS	Necessary	50.00 FS	*15.00 FS
67	1		*HEAD LAMP CLIPS	Not Necessary	50.00 FS	*- FS
68	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
69	1		*COOLANT	Not Necessary	100.00 FS	*- FS
70	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
71	1		*TAILGATE WINDSCREEN DAMPING SEAL	Not Necessary	30.00 FS	*- FS
72	1		*TAILGATE WINDSCREEN INNER SEAL	Not Necessary	50.00 FS	*- FS
73	1		*TAILGATE CHROME GARNISH CLIPS	Necessary	50.00 FS	*15.00 FS
74	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*15.00 FS
75	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
76	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*40.00 FS
77	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*15.00 FS
78	1		*REAR FLOOR PANEL SEALANT	Not Necessary	80.00 FS	*- FS
79	1		*REAR FENDER SEALANT	Not Necessary	80.00 FS	*- FS
80	1		*REAR FENDER INNER TRIM CLIPS	Necessary	50.00 FS	*20.00 FS
81	1		*REAR FENDER QUARTER GLASS SEALANT	Not Necessary	80.00 FS	*- FS
82	1		*REAR FENDER QUARTER GLASS DAMPING SEAL	Not Necessary	30.00 FS	*- FS
83	1		*FRONT & REAR NO PLATE & CASING	Front Bent / Rear Serviceable	200.00 FS	*45.00 FS
84	1		*REVERSE CAMERA	Not Necessary	600.00 FS	*- FS
85	1		*SET REVERSE SENSOR	Damaged	300.00 FS	*220.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>43,678.30</b>	<b>10,839.90</b>
<b>- List Item Discount on L Items 25.00/25.00% (S\$)</b>	10,379.58	2,593.73
<b>Total Parts (S\$)</b>	<b>33,298.72</b>	<b>8,246.17</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	500.00	80.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS (FRONT)	New	1,600.00	300.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS (FRONT)	New	1,600.00	200.00
4	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS (REAR)	New	2,400.00	1,000.00
5	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS (REAR)	New	2,400.00	800.00
6	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
7	TO RNR A/C CONDENSOR & REFILL GAS TO FACILITATE REPAIRS	New	200.00	0.00
8	TO RNR RADIATOR ASSY & REFILL COOLANT TO FACILITATE REPAIRS	New	200.00	0.00
9	TO RNR TAILGATE MECHANISM TO FACILITATE REPAIRS	New	200.00	60.00
10	TO RNR REVERSE CAMERA TO FACILITATE REPAIRS	New	150.00	30.00
11	TO RNR REAR BUMPER SENSOR TO FACILITATE REPAIRS	New	120.00	40.00
12	TO RNR TAILGATE WINDSCREEN TO FACILITATE REPAIRS	New	300.00	120.00
13	TO RNR REAR FENDER QUARTER GLASS TO FACILITATE REPAIRS	New	200.00	0.00
14	TO RNR FUEL TANK FILLER PIPE TO FACILITATE REPAIRS	New	100.00	0.00
15	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
16	TO RNR REAR EXHAUST & ATTACHMENT PARTS TO FACILITATE REPAIRS	New	300.00	0.00
17	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
			<b>Gross Labour Cost (\$\$)</b>	<b>11,070.00</b>
				<b>2,700.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >