5/20/22, 7:39 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III21011694/REA3Q2

Date: 20/05/2022

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0003256_01

Claimant Vehicle SMD5299Y Insured Vehicle No : PC6603R

No:

Date of Loss: 09/11/2021 Nature of Claim: TP Claim No: MFL2021D0004961

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMD5299Y

Make & Model: HYUNDAI ACCENT, 1.4 (A) Engine No: G4LCJU022876

Reg. Date: 24/08/2018 (Man. Year: 2018) Chassis No: KMHCU41BTKU440059

Colour: White Odometer: 34967 km

Engine Capacity: 1368 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70 R14 Rear Tyre Size: 175/70 R14

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		1,898.80	569.92	1,328.88	69.99
Miscellaneous Items		0.00	0.00	0.00	
Labour		960.00	730.00	230.00	23.96
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	2,858.80	1,299.92	1,558.88	54.53
	Approved Total (Overridden) (S\$)		1,050.00		
	(S\$)	2,858.80	1,050.00	1,808.80	63.27
	+ GST 7.00/7.00% (S\$)	200.12	73.50	126.62	63.27
	Nett Amount (S\$)	3,058.92	1,123.50	1,935.42	63.27
	+ Loss of Use (3.0 x S	60.00/day) (S\$)	180.00		
	+ Doc/s	Search Fee (S\$)	7.45		
	No	ett Liability (S\$)	1,310.95		
	Global Sum	Settlement (S\$)	1,310.00		

INSPECTION

Date Inspected:

Date of Assignment: 16/11/2021

Sng Ah Tee Motor & Panel Service Pte Ltd

14/12/2021 Inspected At: (Pioneer)

Blk 3 Pioneer Road North, #01-18

Singapore 628457

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

5/20/22, 7:39 AM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Apr 2022)

Parts: 144 HYUNDAI ACCENT 1.4 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMD5299Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	418.60 FL	*418.60 FL
2	1		*REAR BUMPER RETAINER LH	Not Necessary	23.20 FL	*- FL
3	1		*REAR BUMPER REINFORCEMENT	Not Necessary	376.50 FL	*- FL
4	10		*REAR BUMPER CLIPS	Necessary	49.00 FL	*49.00 FL
5	1		*REAR BOOT LID	Repair	1,223.90 FL	*- FL
6	1		*REAR BOOT EMBLEM	Necessary	27.50 FL	*27.50 FL
7	1		*REAR BOOT ACCENT LOGO	Necessary	29.80 FL	*29.80 FL
8	1		*TO DIAGNOSE & RESET	Necessary	180.00 FS	*150.00 FS
F=Fra	anchise	part. S=SpcNe	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	2,328.50	674.90
			- List Item Discount on L Items 20.00/20.00% (S\$)			104.98
				Total Parts (S\$)	1,898.80	569.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO KNOCK WELD ,REMOVE & FIX ON ABOVE PARTS	New	400.00	300.00
2	TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS	New	500.00	400.00
3	TO CHECK WIRING	New	30.00	30.00
4	TO APPLY ANTI RUST COATING	New	30.00	0.00
		Gross Labour Cost (S\$)	960.00	730.00
	Report was unsubm	itted during this print-out.		

< END OF ESTIMATES >