

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21011696/EEA3Q2 Q2**Date:** 09/03/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_02

Claimant Vehicle No : SLV1791K **Insured Vehicle No :** GBJ3275C

Date of Loss: 16/11/2021 Nature of Claim: TP Claim No: MFL2021D0005136

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLV1791K**
 Make & Model: BYD E6H, (A) Engine No: 0
 Reg. Date: 22/12/2017 (Man. Year: 2017) Chassis No: LC0CE4DB3H1026329
 Colour: White Odometer: 206169 km
 Engine Capacity: 0 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/65 R17 Rear Tyre Size: 225/65 R17
 Front Left Side: Sailun 4 mm Rear Left Side: Sailun 4 mm
 Front Right Side: Sailun 4 mm Rear Right Side: Sailun 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,718.31	3,561.75	4,156.56	53.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,700.00	1,940.00	2,760.00	58.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,418.31	5,501.75	6,916.56	55.70
+ GST 7.00/7.00% (S\$)	869.28	385.12	484.16	55.70
Nett Amount (S\$)	13,287.59	5,886.87	7,400.72	55.70
+ Loss of Use (7.0 x S\$40.00/day) (S\$)		280.00		
+ Car Rental (7.0 x S\$90.95/day) (S\$)		636.65		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,810.97		
Global Sum Settlement (S\$)		6,810.00		

INSPECTION

Date of Assignment: 16/11/2021

Date Inspected: 17/11/2021 Inspected At: DING AUTO PTE LTD
 31 CORPORATION ROAD
 Singapore 649825

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Jan 2022)
Parts:	M1-MPV	BYD E6H (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV1791K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH DOOR PANEL	Dented	1,291.39 F	*1,291.39 FL
2	1		*FRONT RH SIDE MIRROR ASSY	Broken	525.32 F	*525.32 FL
3	1		*FRONT RH DOOR GLASS	Cut	149.76 F	*149.76 FL
4	1		*FRONT RH OUTER DOOR HANDLE	Broken	403.20 F	*403.20 FL
5	1		*FRONT RH DOOR LOCK	Not Necessary	160.13 F	*- FL
6	1		*FRONT RH DOOR UPPER WINDOW FRAME BLACK FILM	Necessary	16.13 F	*16.13 FL
7	1		*FRONT RH POWER WINDOW REGULATOR ASSY	Not Necessary	269.57 F	*- FL
8	1		*FRONT RH DOOR B-PILLAR BLACK FILM	Necessary	16.13 F	*16.13 FL
9	1		*FRONT RH OUTER DOOR HANDLE BASE (NPA)	Not Necessary	0.00 F	*- FL
10	1		*SIDE SKIRT RH	Repair	92.16 F	*- FL
11	1		*FRONT RH OUTER DOOR WEATHERSTRIP MOULDING	Not Necessary	145.15 F	*- FL
12	1		*FRONT RH OUTER DOOR HANDLE COVER (NPA)	Not Necessary	0.00 F	*- FL
13	1		*FRONT RH POWER WINDOW REGULATOR MOTOR (NPA)	Not Necessary	0.00 F	*- FL
14	1		*REAR RH DOOR PANEL	Dented	1,223.42 F	*1,223.42 FL
15	1		*REAR RH UPPER DOOR HINGE	Not Necessary	16.13 F	*- FL
16	1		*REAR RH LOWER DOOR HINGE	Not Necessary	16.13 F	*- FL
17	1		*REAR RH DOOR CHECK	Not Necessary	47.23 F	*- FL
18	1		*REAR RH POWER WINDOW REGULATOR	Not Necessary	259.20 F	*- FL
19	1		*REAR RH POWER WINDOW REGULATOR MOTOR (NPA)	Not Necessary	0.00 F	*- FL
20	1		*REAR RH DOOR GLASS	Not Necessary	147.46 F	*- FL
21	1		*FRONT RH DOOR FRAME WEATHERSTRIP	Not Necessary	396.29 F	*- FL
22	1		*REAR RH DOOR FRAME WEATHERSTRIP	Not Necessary	555.03 F	*- FL
23	1		*REAR RH DOOR B-PILLAR BLACK FILM	Necessary	13.82 F	*13.82 FL
24	1		*REAR RH DOOR UPPER WINDOW FRAME BLACK FILM	Necessary	13.82 F	*13.82 FL
25	1		*REAR RH DOOR REAR FRAME SECTION BLACK FILM	Necessary	13.82 F	*13.82 FL
26	1		*REAR RH OUTER DOOR WEATHERSTRIP MOULDING	Not Necessary	177.41 F	*- FL
27	1		*REAR RH TYRE RIM	Cut	564.48 FS	*80.00 FS
28	1		*REAR RH DOOR GLASS RUN	Not Necessary	106.44 F	*- FL
29	1		*REAR BUMPER COVER	Repair	315.76 F	*- FL
30	1		*REAR RH BUMPER REFLECTOR	Not Necessary	27.65 F	*- FL

Report was unsubmitted during this print-out.

3/9/22, 11:52 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
31	1		*FRONT RH DOOR GLASS WINDOW UPPER GUIDE CHANNEL	Not Necessary	35.14 F	*- FL
32	1		*SET REAR BUMPER CLIP	Necessary	70.00 FS	*30.00 FS
33	1		*REAR RH DOOR STICKER	Necessary	250.00 FS	*50.00 FS
34	1		*FRONT RH DOOR STICKER	Necessary	250.00 FS	*50.00 FS
35	1		*SET SIDE SKIRT CLIP	Necessary	60.00 FS	*20.00 FS
36	1		*SET DOOR MOULDING CLIP	Not Necessary	55.00 FS	*- FS
37	1		*UPPER FRONT GLASS GUIDE CHANNEL ASSY ,FRONT WINDOW ,R	Bent	35.14 F	*35.14 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					7,718.31	3,931.95
- List Item Discount on L Items 0.00/10.00% (\$)					0.00	370.20
Total Parts (\$)					7,718.31	3,561.75
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO STRAIGHTEN AND PANEL BEAT OF ACCIDENT AFFECTED AREA	New	1,600.00	600.00
2	TO RUST PROOFING OF THE AFFECTED AREA	New	180.00	30.00
3	TO REMOVE AND REFIT OF NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR	New	300.00	0.00
4	TO DIAGNOSTIC CHECK WIRING AND LIGHTING SYSTEM AND CLEAR FAULT CODE	New	280.00	100.00
5	TO TRANSFER OF BOTH FRONT AND REAR DOOR MECHANISM TO NEW DOOR AND PERFORM WATER SEEPAGE TEST	New	260.00	100.00
6	TO CONDUCT TYRE BALANCING AND WHEEL ALIGNMENT	New	160.00	60.00
7	TO CHECK AND REPAIR WIRE HARNESS	New	170.00	0.00
8	TO RESPRAY REAR BUMPER	New	250.00	200.00
9	TO RESPRAY REAR END PANEL	New	250.00	0.00
10	TO RESPRAY REAR QUARTER PANEL	New	250.00	200.00
11	TO RESPRAY REAR DOOR PANEL	New	250.00	200.00
12	TO RESPRAY FRONT DOOR PANEL	New	250.00	200.00
13	TO RESPRAY SIDE SKIRT RH	New	250.00	200.00
14	TO RESPRAY FRONT RH SIDE MIRROR	New	250.00	50.00
Gross Labour Cost (\$\$)			4,700.00	1,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >