



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD	INV No.	AC2303889
3 ANSON ROAD #16-00	INV Date	19/06/2023
SPRINGLEAF TOWER	Reference	CC6/CTI21011698/Apa3q2
SINGAPORE 079909	Code	CTI

### PROFESSIONAL SERVICE FEE

Vehicle No.	SLM 5344P
Insured Veh.	SJK 1702A
Claim No.	SNM21D206612/C02
Policy No.	DMPCSNW00066712101
Accident Date	15/11/2021
Inspection Date	16/11/2021

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (8%)</b>	<b>32.00</b>
<b>Grand Total</b>	<b>432.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Ref: CC6/CTI21011698/Apa3q2 Date: 19/06/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJK 1702A	Veh. Inspected	SLM 5344P
Policy No.	DMPCSNW00066712101	Coverage (\$)	0.00
Claim No.	SNM21D206612/C02	Excess (\$)	0.00
Assign From		Assign Date	16/11/2021
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA SIENTA	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	NSP1707044132	Colour	SILVER
Odometer	98423 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/60 R15	YOKOHAMA	6 mm
L/H Front Tyre	185/60 R15	YOKOHAMA	6 mm
R/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm
L/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	15/11/2021	Inspection Date	16/11/2021
Survey held at	J-MART MOTOR PTE LTD BLK 5 DEFU LANE 10 #01-578 DEFU INDUSTRIAL PARK C SINGAPORE 539186		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 5344P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	TAILGATE	DISTORTED	1,132.20	1,132.20
1	TAILGATE LOCK	DAMAGED	467.00	372.00
1	TAILGATE OUTER GARNISH	CRACKED	283.00	283.00
1	TAILGATE INNER HANDLE	NOT NECESSARY	30.20	-
1	TAILGATE W/STRIP	CUT	385.00	385.00
2	TAILGATE REFLECTOR	N/S CUT	669.00	334.50
1	TAILGATE TRIMBOARD	NOT NECESSARY	138.00	-
2	REAR NO PLATE LAMP	NOT NECESSARY	128.20	-
2	TAILLAMP	N/S CUT	1,029.60	514.80
1	REAR BUMPER	DEFORMED	418.20	418.20
2	REAR BUMPER RETAINER	NECESSARY	141.00	141.00
2	REAR BUMPER HOLDER	NOT NECESSARY	120.00	-
2	REAR BUMPER PAD RH LH	CUT	258.20	258.20
1	REAR BUMPER CENTRE PAD	DEFORMED	190.00	190.00
1	REAR BUMPER TOW HOOK COVER	CUT	32.00	32.00
2	REAR BUMPER REFLECTOR	NOT NECESSARY	119.60	-
4	REAR BUMPER CLIPS	NECESSARY	20.00	20.00
1	TOOL BOX	DEFORMED	432.40	371.00
1	KEY LOCK SENSOR	DAMAGED	135.00	135.00
1	END PANEL	DENTED	890.20	696.00
1	END PANEL INNER GARNISH	DEFORMED	147.50	147.50
1	SPARE TYRE CARDBOARD	DEFORMED	466.40	466.40
1	TAILGATE LOGO	NECESSARY	72.20	72.20
	LESS 25% DISCOUNT		-1,926.23	-1,492.25
			5,778.67	4,476.75
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR W/SCREEN GUM (SN)	NECESSARY	50.00	50.00
1	REAR W/SCREEN SEAL (SN)	NECESSARY	30.00	30.00
1	REVERSE SENSOR (SN)	DAMAGED	250.00	200.00
1	CAMERA (SN)	NOT NECESSARY	400.00	-

Report Ref No. CC6/CTI21011698/Apa3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR NO PLATE (SN)	DEFORMED	40.00	40.00
			770.00	320.00
	<b>LABOUR</b>			
	PANEL BEATING.		1,000.00	900.00
	SPRAY PAINTING.		1,000.00	800.00
	WIRING.		30.00	30.00
	RUST PROOFING .		80.00	60.00
	UPHOLSTERY .		120.00	80.00
	TRANSFER TAILGATE FITTING.		80.00	80.00
	REMOVE & REFIT REAR W/SCREEN .		120.00	120.00
			2,430.00	2,070.00
	<b>GRAND TOTAL</b>		<b>8,978.67</b>	<b>6,866.75</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>5,500.00</b>

Report Ref No. CC6/CTI21011698/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



# LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## PHOTOGRAPHS FOR VEHICLE NO. SLM 5344P

## INSPECTION





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLM 5344P

RE-INSPECTION






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

