

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21011699/AQCN2**Date:** 22/02/2022**REFERENCE**

Insured/Claimant: NARVINDER SINGH Policy No: 1900171694-01
Date of Loss: 12/11/2021 Nature of Claim: OD Claim No: 9799321385SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMP5965U**
Make & Model: AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A) Engine No: CVK086254
Reg. Date: 30/09/2019 (Man. Year: 2019) Chassis No: WAUZZZF55KA068566
Colour: White Odometer: 30400 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$153,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 255/35R19 Rear Tyre Size: 255/35R19
Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,024.00	9,336.72	16,687.28	64.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,772.00	3,572.00	4,200.00	54.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	33,796.00	12,908.72	20,887.28	61.80
- Excess (S\$)	1,600.00	1,600.00	0.00	0.00
(S\$)	32,196.00	11,308.72	20,887.28	64.88
+ GST 7.00/7.00% (S\$)	2,253.72	791.61	1,462.11	64.88
Nett Amount (S\$)	34,449.72	12,100.33	22,349.39	64.88

INSPECTION

Date of Assignment: 17/11/2021
Date Inspected: 16/11/2021 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,251.00 FS	*1,800.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	407.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	71.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE-CENTER	Not Necessary	196.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT LOWER-CENTER	Not Necessary	228.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE-LH	Not Necessary	63.00 FS	*- FS
7	1		*RADIATOR GRILLE	Not Necessary	2,326.00 FS	*- FS
8	2		*FRONT PARKING AID SENSOR SUPPORT-LH/RH	Not Necessary	102.00 FS	*- FS
9	1		*FRONT AIR GUIDE-LH	Not Necessary	474.00 FS	*- FS
10	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	124.00 FS	*- FS
11	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	845.00 FS	*- FS
12	1		*FRONT BUMPER GUIDE SECTION-LH	Cracked	36.00 FS	*28.72 FS
13	1		*FRONT BUMPER TOP COVER	Not Necessary	127.00 FS	*- FS
14	1		*CAUTION STICKER	Not Necessary	14.00 FS	*- FS
15	1		*AIRCON STICKER	Not Necessary	8.00 FS	*- FS
16	1		*FRONT BUMPER LOCK CARRIER	Not Necessary	137.00 FS	*- FS
17	2		*FRONT BUMPER SUPPORT-LH/RH	Not Necessary	58.00 FS	*- FS
18	1		*FRONT RADIATOR GRILLE UPPER BRACKET	Not Necessary	189.00 FS	*- FS
19	1		*HORN-LH	Not Necessary	126.00 FS	*- FS
20	1		*HORN BRACKET-LH	Not Necessary	29.00 FS	*- FS
21	1		*FRONT PARKING AID SENSOR (Npa)	Not Necessary	0.00 FS	*- FS
22	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS
23	1		*FRONT FENDER-LH	Dented	1,060.00 FS	*848.00 FS
24	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	53.00 FS	*- FS
25	1		*FRONT FENDER CLOSING ELEMENT-LH	Damaged	74.00 FS	*59.04 FS
26	1		*FRONT FENDER BRACKET CENTER-LH	Damaged	35.00 FS	*27.92 FS
27	5		*POP RIVET	Not Necessary	17.00 FS	*- FS
28	1		*FRONT FENDER BRACE-LH	Bent	118.00 FS	*94.40 FS
29	1		*FRONT FENDER BRACKET-LH	Not Necessary	49.00 FS	*- FS
30	1		*FRONT FENDER TRIM-LH	Necessary	164.00 FS	*130.80 FS
31	1		*FRONT WHEEL HOUSING LINER-LH	Not Necessary	275.00 FS	*- FS
32	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	169.00 FS	*- FS
33	1		*FRONT WHEEL SPOILER-LH	Not Necessary	73.00 FS	*- FS
34	1		*FRONT SPOILER-LH	Not Necessary	35.00 FS	*- FS
35	1		*FRONT FENDER FLEDGE COVER-LONG	Not Necessary	36.00 FS	*- FS
36	1		*FRONT FENDER FLEDGE COVER-SHORT	Deformed	16.00 FS	*12.24 FS
37	1		*BONNET	Repair	3,312.00 FS	*- FS
38	6		*CAP NUT	Not Necessary	24.00 FS	*- FS
39	1		*BONNET ATTACHMENT PARTS	Not Necessary	123.00 FS	*- FS
40	2		*BONNET HINGE-LH/RH	Not Necessary	838.00 FS	*- FS
41	3		*BONNET IMPACT PROTECTION-CENTER/LH/RH	Not Necessary	84.00 FS	*- FS
42	1		*BONNET STRIKER	Not Necessary	50.00 FS	*- FS
43	1		*BONNET LOCK	Not Necessary	214.00 FS	*- FS
44	1		*HEADLIGHT-LH	Cut	7,902.00 FS	*6,321.60 FS
45	1		*HEADLIGHT CONTROL UNIT	Not Necessary	751.00 FS	*- FS
46	1		*HEADLIGHT POWER MODULE	Not Necessary	758.00 FS	*- FS
47	1		*HEADLIGHT HEAT SINK-LH	Not Necessary	1,153.00 FS	*- FS
48	3		*HEADLIGHT SPACER	Not Necessary	122.00 FS	*- FS
49	1		*LIFT CYLINDER-LH	Not Necessary	198.00 FS	*- FS
50	1		*LIFT CYLINDER HOSE	Not Necessary	86.00 FS	*- FS
51	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
52	1		*SUNDRIES	Necessary	350.00 FS	*13.20 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 26,024.00 9,336.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER,LHS FRONT FENDER,BONNET AND LHS HEADLIGHT.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	3,200.00	1,000.00
4	TO RESPRAY FRONT BUMPER,BONNET,HINGES AND LHS FRONT FENDER	New	3,500.00	1,650.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
			Gross Labour Cost (\$\$)	7,772.00
				3,572.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >