

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21011700/ATCN2**Date:** 04/05/2022**REFERENCE**

Insured/Claimant: YEOH LAI ANN Policy No: 1900152327-02
Date of Loss: 08/11/2021 Nature of Claim: OD Claim No: 9554962775SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **EY1212H**
Make & Model: AUDI A3, 999cc TFSI S-TRONIC (A) Engine No: CHZ529742
Reg. Date: 20/09/2017 (Man. Year: 2017) Chassis No: WAUZZZ8V7J1012155
Colour: Blue Odometer: 37835 km
Engine Capacity: 999 cc
Market Value/New Car Price: S\$80,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 4,887.00 | 3,200.00 | 1,687.00 | 34.52 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 3,192.00 | 1,522.00 | 1,670.00 | 52.32 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 8,079.00 | 4,722.00 | 3,357.00 | 41.55 |
| - Excess (S\$) | 1,500.00 | 1,500.00 | 0.00 | 0.00 |
| (S\$) | 6,579.00 | 3,222.00 | 3,357.00 | 51.03 |
| + GST 7.00/7.00% (S\$) | 460.53 | 225.54 | 234.99 | 51.03 |
| Nett Amount (S\$) | 7,039.53 | 3,447.54 | 3,591.99 | 51.03 |

INSPECTION

Date of Assignment: 17/11/2021
Date Inspected: 16/11/2021 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$430.00 NETT)

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--------------------------------|---------------|-------------|--------------|
| 1 | 1 | | *FRONT DOOR-LH | Dented | 3,039.00 FS | *3,039.00 FS |
| 2 | 1 | | *BUNGS | Not Necessary | 4.00 FS | *- FS |
| 3 | 1 | | *FRONT DOOR OUTER SEAL-LH | Necessary | 161.00 FS | *161.00 FS |
| 4 | 1 | | *BONDING AGENT | *Check | 49.00 FS | *- FS |
| 5 | 1 | | *CLEANING SOLUTION | *Check | 68.00 FS | *- FS |
| 6 | 1 | | *APPLICATOR | *Check | 8.00 FS | *- FS |
| 7 | 1 | | *FRONT DOOR ATTACHMENT PARTS | Not Necessary | 241.00 FS | *- FS |
| 8 | 1 | | *FRONT DOOR CATCH-LH | *Check | 105.00 FS | *- FS |
| 9 | 1 | | *FRONT WIND MIRROR MOUNTING-LH | Not Necessary | 1,012.00 FS | *- FS |
| 10 | 1 | | *SUNDRIES | *Check | 200.00 FS | *- FS |

F=Franchise part. S=SpcNett.

| | | |
|-------------------------|-----------------|-----------------|
| Total Parts (\$) | 4,887.00 | 3,200.00 |
|-------------------------|-----------------|-----------------|

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|---|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TO REMOVE AND TRANSFER LHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES | New | 350.00 | 280.00 |
| 2 | TO DISMANTLE AND RENEW LHS FRONT DOOR.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED | New | 1,050.00 | 500.00 |
| 3 | TO RESPRAY LHS FRONT DOOR,LHS WIND MIRROR COVER AND DOOR HANDLE | New | 1,600.00 | 550.00 |
| 4 | TO CARRY OUT DIAGNOSTIC CHECK | New | 192.00 | 192.00 |
| Gross Labour Cost (\$\$) | | | 3,192.00 | 1,522.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >