

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CC3/AIG21011701/ATCN2**Date:** 03/01/2022**REFERENCE**Insured/Claimant: LEE HENG THYE
Date of Loss: 11/11/2021Policy No:
Nature of Claim: OD Claim No: 0798295430SG**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	SGK93R	Engine No:	CVN004995
Make & Model:	AUDI A4, 1.4 TFSI S TRONIC (A)	Chassis No:	WAUZZZF40GA039359
Reg. Date:	31/03/2016 (Man. Year: 2016)	Odometer:	49302 km
Colour:	White		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$70,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,986.00	12,862.00	9,124.00	41.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,694.00	2,542.00	6,152.00	70.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,680.00	15,404.00	15,276.00	49.79
- Excess (S\$)	550.00	550.00	0.00	0.00
(S\$)	30,130.00	14,854.00	15,276.00	50.70

+ GST 7.00/7.00% (S\$)

2,109.10

1,039.78

1,069.32

50.70

Nett Amount (S\$)**32,239.10****15,893.78****16,345.32****50.70**INSPECTION

Date of Assignment: 17/11/2021

Date Inspected: 16/11/2021

Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,111.00 FS	*1,688.80 FS
2	1		*FRONT BUMPER FIXING PARTS Npa	Not Necessary	0.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIPS	Not Necessary	71.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE-CENTER	Cracked	196.00 FS	*156.40 FS
5	1		*FRONT BUMPER CLOSING ELEMENT LOWER-CENTER	Not Necessary	210.00 FS	*- FS
6	2		*FRONT BUMPER AIR GUIDE-LH/RH	Not Necessary	126.00 FS	*- FS
7	1		*RADIATOR GRILLE	Cracked	1,152.00 FS	*921.60 FS
8	2		*FRONT BUMPER AIR GUIDE GRILLE-LH/RH	Not Necessary	270.00 FS	*- FS
9	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	124.00 FS	*99.20 FS
10	1		*FRONT BUMPER REINFORCEMENT BEAM	Dented	845.00 FS	*675.60 FS
11	1		*FRONT BUMPER TOP COVER	Cracked	127.00 FS	*101.60 FS
12	2		*FRONT BUMPER GUIDE SECTION-LH/RH	Not Necessary	72.00 FS	*- FS
13	1		*CAUTION STICKER	Necessary	14.00 FS	*10.88 FS
14	1		*AIR COND STICKER	Necessary	8.00 FS	*5.68 FS
15	1		*FRONT BUMPER BRACKET-LH	Not Necessary	228.00 FS	*- FS
16	1		*LOCK CARRIER TOP BRACKET	Cracked	137.00 FS	*109.60 FS
17	2		*LOCK CARRIER SUPPORT-LH/RH	Necessary	58.00 FS	*44.96 FS
18	1		*HORN HIGH TONE-LH	Not Necessary	126.00 FS	*- FS
19	1		*HORN BRACKET-LH	Not Necessary	29.00 FS	*- FS
20	1		*BONNET	Dented	3,246.00 FS	*2,596.80 FS
21	1		*BONNET ATTACHMENT PARTS	Not Necessary	412.00 FS	*- FS
22	2		*BONNET HINGE-LH/RH	Not Necessary	610.00 FS	*- FS
23	1		*BONNET IMPACT PROTECTION-CENTER/LH/RH 3 Pcs	Necessary	84.00 FS	*65.68 FS
24	1		*BONNET BOWDEN CABLE	Not Necessary	58.00 FS	*- FS
25	1		*BONNET RELEASE LEVER	Not Necessary	14.00 FS	*- FS
26	1		*BONNET BOWDEN CABLE INNER-CENTER	Not Necessary	58.00 FS	*- FS
27	1		*BONNET BOWDEN CABLE INNER COVER	Not Necessary	10.00 FS	*- FS
28	1		*BONNET STRIKER-LH	Not Necessary	50.00 FS	*- FS
29	1		*BONNET LID LOCK	Not Necessary	214.00 FS	*- FS
30	1		*LED HEADLIGHT-LH	Cracked	7,693.00 FS	*6,154.40 FS
31	1		*LIFT CYLINDER-LH	Damaged	210.00 FS	*167.60 FS
32	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	93.00 FS	*- FS
33	1		*LOCK CARRIER	Not Necessary	1,016.00 FS	*- FS
34	1		*RADIATOR SUPPORT-LH	Not Necessary	38.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
35	1		*OUTSIDE TEMPERATURE SENSOR HOLDER	Not Necessary	19.00 FS	*- FS
36	6		*RADIATOR COOLANT	Not Necessary	267.00 FS	*- FS
37	2		*RADIATOR AIR GUIDE OUTER-LH/RH	Not Necessary	56.00 FS	*- FS
38	2		*RADIATOR AIR GUIDE INNER-LH/RH	Not Necessary	24.00 FS	*- FS
39	1		*RADIATOR AIR GUIDE-UPPER	Not Necessary	16.00 FS	*- FS
40	1		*RADIATOR AIR GUIDE-LOWER	Not Necessary	22.00 FS	*- FS
41	1		*HEADLIGHT ELECTRONIC POWER MODULE	Not Necessary	761.00 FS	*- FS
42	1		*HEADLIGHT CONTROL UNIT	Not Necessary	751.00 FS	*- FS
43	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
44	1		*SUNDRIES	Necessary	300.00 FS	*3.20 FS
					Total Parts (\$)	21,986.00
						12,862.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO RENEW AND REINSTALL AIRCON CONDENSER,CHARGED AIR COOLER AND RADIATOR.TO RENEW ADDITIONAL RADIATOR.CHECK ELECTRICAL FANS AND CONTROL UNIT.PRESSURISE COOLING SYSTEM.TO CARRY OUT VACUUM AND REGAS	New	1,400.00	0.00
4	TO DISMANTLE AND RENEW FRONT BUMPER,BONNET AND LHS HEADLIGHT.TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	4,200.00	1,000.00
5	TO RESPRAY FRONT BUMPER,BONNET AND HINGES	New	2,000.00	1,100.00
6	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	192.00
Gross Labour Cost (S\$)			8,694.00	2,542.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >