

|   |   |   |        |   |   |   |   |      |   |   |             |
|---|---|---|--------|---|---|---|---|------|---|---|-------------|
| ⏪ | < | 1 | of 2 ? | > | ⏩ | ↺ | ↻ | 100% | ⏴ | ⏵ | Find   Next |
|---|---|---|--------|---|---|---|---|------|---|---|-------------|



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |   |                          |                |
|--|---|--------------------------|----------------|
| EQ INSURANCE COMPANY LTD   |   | Ref: CS/EQI21011707/Uqf3 |                |
| 5 MAXWELL ROAD   |   | Date: 17/11/2021         |                |
| #17-00 TOWER BLOCK   |   |                          |                |
| MND COMPLEXSINGAPORE 069110  |   | Code: EQI                |                |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>  |   |                          |                |
| <b>Insured Veh.</b>  | SML 4045C   | <b>Veh. Inspected</b>    | SMP 1626A      |
| <b>Policy No.</b>  |   | <b>Coverage (\$)</b>     | 0.00           |
| <b>Claim No.</b>   | DM21HO01707/JT  | <b>Excess (\$)</b>       | 0.00           |
| <b>Assign From</b>   | JAIME TAY   | <b>Assign Date</b>       | 17/11/2021     |
| <b>2. Vehicle Particulars &amp; Condition</b>  |   |                          |                |
| <b>Make &amp; Model</b>  |   | <b>c.c</b>               | 0              |
| <b>Engine No.</b>  | HIDDEN  | <b>Year of Reg.</b>      |                |
| <b>Chassis No.</b>   |   | <b>Colour</b>            |                |
| <b>Odometer</b>  | -   | <b>Steering</b>          |                |
| <b>Brakes</b>  |   | <b>Modification</b>      |                |
| <b>General</b>   |   |                          |                |
| <b>3. Conditions of Tyres</b>  |   |                          |                |
|  | <b>Size</b>   | <b>Make</b>              | <b>Balance</b> |
| <b>R/H Front Tyre</b>  |   |                          | mm             |
| <b>L/H Front Tyre</b>  |   |                          | mm             |
| <b>R/H Rear Tyre</b>   |   |                          | mm             |
| <b>L/H Rear Tyre</b>   |   |                          | mm             |
| <b>4. Description of Damages</b>   |   |                          |                |
|  |   |                          |                |
| <b>5. General Information</b>  |   |                          |                |
| <b>Accident Date</b>   | 13/11/2021  | <b>Inspection Date</b>   | 17/11/2021     |
| <b>Survey held at</b>  | HUP MOTOR TRADING & SERVICE<br>BLK 9004 TAMPINES ST 93<br>#01-120<br>SINGAPORE 528838 |                          |                |
| <b>5a. Remarks</b>   |   |                          |                |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |                          |                |