

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21011718/UEA3Q2**Date:** 11/05/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900021061
Claimant Vehicle No :	SGX592Z	Insured Vehicle No :	S4246CD
Date of Loss:	16/11/2021	Nature of Claim:	TP
		Claim No:	2474260490SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGX592Z	Engine No:	B5254T4171894
Make & Model:	VOLVO V50, T5 (A)	Chassis No:	YV1MW675982370389
Reg. Date:	10/08/2007 (Man. Year: 2007)	Odometer:	182048 km
Colour:	Blue		
Engine Capacity:	2521 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,947.00	2,385.00	5,562.00	69.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,660.00	2,040.00	1,620.00	44.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,607.00	4,425.00	7,182.00	61.88
Approved Total (Overridden) (S\$)		3,500.00		
(S\$)	11,607.00	3,500.00	8,107.00	69.85
+ GST 7.00/7.00% (S\$)	812.49	245.00	567.49	69.85
Nett Amount (S\$)	12,419.49	3,745.00	8,674.49	69.85
+ Car Rental (5.0 x S\$120.00/day) (S\$)		600.00		
Nett Liability (S\$)		4,345.00		

INSPECTION

Date of Assignment:	17/11/2021	
Date Inspected:	18/11/2021	Inspected At: Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412 Singapore 539195
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH DOOR	Repair	2,500.00 FL	*- FL
2	1		*FRONT LH DOOR PROTECTOR	Bent	185.00 FL	*185.00 FL
3	1		*REAR LH DOOR	Badly Dented	2,500.00 FL	*2,100.00 FL
4	1		*REAR LH DOOR PROTECTOR	Bent	185.00 FL	*185.00 FL
5	1		*REAR LH DOOR LOWER MOULDING	Cut	90.00 FL	*90.00 FL
6	1		*REAR LH DOOR POWER WINDOW REGULATOR	Not Necessary	428.00 FL	*- FL
7	1		*REAR LH DOOR POWER WINDOW MOTOR	Not Necessary	652.00 FL	*- FL
8	1		*FRONT LH DOOR MOULDING	Missing	90.00 FL	*90.00 FL
9	1		*REAR BUMPER	Repair	2,200.00 FL	*- FL
10	1		*REAR LH FENDER (NPA)	Repair	0.00 FL	*- FL
11	1		*LH LOCKER PANEL (NPA)	Repair	0.00 FL	*- FL
12	1		*LH DOOR CENTER PILLAR (NPA)	Repair	0.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	8,830.00	2,650.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	883.00	265.00
Total Parts (\$\$)	7,947.00	2,385.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGE	New	1,850.00	900.00
2	SPRAY PAINTING	New	1,450.00	900.00
3	TRANSFER DOOR FITTINGS	New	120.00	120.00
4	SPRAY TUFF COAT	New	120.00	60.00
5	CONDUCT WHEEL ALIGNMENT	New	120.00	60.00
Gross Labour Cost (\$)			3,660.00	2,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >