

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21011720/R1QY3N2**Date:** 04/01/2022**REFERENCE**Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00120452000

**Claimant Vehicle  
No :** SCW8777H**Insured Vehicle  
No :** GBJ476J

Date of Loss: 03/11/2021

Nature of Claim: TP

Claim  
No: SNM21D206337/C2/IRENE**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SCW8777H**

Make &amp; Model: VOLKSWAGEN SHARAN, 1.8 (A)

Engine No: CCZ481827

Reg. Date: 30/04/2015 (Man. Year: 2015)

Chassis No: WVVZZZ7NZFV034556

Colour: Blue

Odometer: 98831 km

Engine Capacity: 1984 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 245/35 ZR19

Rear Tyre Size: 245/35 ZR19

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,206.70	2,662.20	544.50	16.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,380.00	740.00	640.00	46.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,586.70</b>	<b>3,402.20</b>	<b>1,184.50</b>	<b>25.82</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,700.00</b>		
<b>(S\$)</b>	4,586.70	2,700.00	1,886.70	41.13
<b>+ GST 7.00/7.00% (S\$)</b>	321.07	189.00	132.07	41.13
<b>Nett Amount (S\$)</b>	<b>4,907.77</b>	<b>2,889.00</b>	<b>2,018.77</b>	<b>41.13</b>

**INSPECTION**

Date of Assignment: 17/11/2021

Date Inspected: 19/11/2021

Inspected At:

Ethoz Group Ltd (HQ)  
30 Bukit Batok Crescent  
Singapore 658075

Estimated Period of Repair: 3.0 days

**Adjuster:** MOHD RASUL**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 04 Jan 2022)
<b>Parts:</b>	M1-MPV	VOLKSWAGEN SHARAN 1.8 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SCW8777H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR LH	Bent	1,890.00 FL	*1,456.00 FL
2	1		*FRONT DOOR WEATHERSTRIP LH	Necessary	392.00 FL	*288.00 FL
3	1		*FRONT DOOR RIVET PIN	Necessary	150.00 FL	*150.00 FL
4	1		*WING MIRROR ASSY LH	Cracked	784.00 FL	*784.00 FL
5	1		*WING MIRROR COVER LH	Cracked	144.00 FL	*144.00 FL
6	1		*WING MIRROR SIGNAL LENS LH	Scratched	203.00 FL	*136.00 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,563.00</b>	<b>2,958.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	356.30	295.80
<b>Total Parts (\$\$)</b>	<b>3,206.70</b>	<b>2,662.20</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR TO FACILITATE REPAIR	New	600.00	300.00
2	TO RESPRAY AFFECTED AREAS	New	600.00	350.00
3	TO REMOVE AND TRANSFER DOOR COMPONENTS	New	150.00	60.00
4	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	New	30.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,380.00</b>	<b>740.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >