

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21011724/EVY3N2**Date:** 18/02/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNA00106642100

**Claimant Vehicle No :** SLG2890E **Insured Vehicle No :** SCY27G

Date of Loss: 06/11/2021 Nature of Claim: TP Claim No: SNM21D206436/C02/LEWLC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SLG2890E**

Make & Model: HONDA SHUTTLE HYBRID, 1.5 (A) Engine No: LEB4259733

Reg. Date: 27/09/2016 (Man. Year: 2016) Chassis No: GP71040457

Colour: Silver Odometer: 144352 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 185/55R15 Rear Tyre Size: 185/55R15

Front Left Side: Dunlop 4 mm Rear Left Side: Dunlop 4 mm

Front Right Side: Dunlop 4 mm Rear Right Side: Dunlop 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,988.00	1,970.00	2,018.00	50.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,620.00	870.00	750.00	46.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>5,608.00</b>	<b>2,840.00</b>	<b>2,768.00</b>	<b>49.36</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>2,250.00</b>		
<b>(\$\$)</b>	5,608.00	2,250.00	3,358.00	59.88
<b>+ GST 7.00/7.00% (\$\$)</b>	392.56	157.50	235.06	59.88
<b>Nett Amount (\$\$)</b>	<b>6,000.56</b>	<b>2,407.50</b>	<b>3,593.06</b>	<b>59.88</b>

**INSPECTION**

Date of Assignment: 17/11/2021

Date Inspected: 18/11/2021 Inspected At: 60 JALAN LAM HUAT# 04-35/36  
CARROS CENTRE, 737869  
SINGAPORE.  
REPAIRER: LION CITY RENTALS PTE LTD

Estimated Period of Repair: 3.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 18 Feb 2022)	
<b>Parts:</b>	N/A	HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLG2890E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*F/R DOOR	Dented	1,575.00 FL	*1,250.00 FL
2	1		*F/R DOOR LOCK ASSY	Not Necessary	550.00 FL	*- FL
3	1		*F/R DOOR MIRROR ASSY	Cut	850.00 FL	*695.00 FL
4	1		*F/R DOOR WINDOW REGULATOR	Bent	480.00 FL	*480.00 FL
5	1		*F/R DOOR WINDOW MOTOR ASSY	Not Necessary	680.00 FL	*- FL
6	1		*RH SIDE SKIRT	Repair	750.00 FL	*- FL
7	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
					<b>Sub Total (\$\$)</b>	<b>4,965.00</b>
					<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>977.00</b>
					<b>Total Parts (\$\$)</b>	<b>3,988.00</b>
						<b>1,970.00</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO LABOUR CHARGE FOR REMOVING F/R SIDE MIRROR AND FRONT DOOR (RH) TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS.AND TO PANEL BEAT AND TO STRAIGHTEN RH SIDE SKIRT	New	700.00	350.00
2	TO RESPRAY FRONT RH DOOR AND RH SIDE SKIRT	New	600.00	440.00
3	TRANSFER DOOR MECHANISM TO FACILITATE REPAIRS AND REPLACEMENT OF PARTS	New	120.00	50.00
4	TO CONFIGURE AND RESET DOOR KEYLESS SECURITY SYSTEM BACK TO FACTORY SPECIFICATION	New	200.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,620.00</b>	<b>870.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >