

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
	LONPAC INSURANCE BHD		Ref:	CS3/LPC21011726/Gvf3e2
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555	Date:	29/11/2021
			Code:	LPC2
1.	Policy Particulars :- (THIRD PARTY CLAIM)			
	Insured Veh.	YP 8668R	Veh. Inspected	GBG 8690U
	Policy No.		Coverage (\$)	0.00
	Claim No.	21/21/21/VC00/025037	Excess (\$)	0.00
	Assign From	GERALD POH	Assign Date	17/11/2021
2. Vehicle Particulars & Condition				
	Make & Model	FIAT DOBLO CARGO MAXI 1.6	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	ZFA26300006H31333	Colour	GREY
	Odometer	119935 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/60 R16	HABILEAD	6 mm
	L/H Front Tyre	205/60 R16	HABILEAD	6 mm
	R/H Rear Tyre	205/60 R16	HABILEAD	6 mm
	L/H Rear Tyre	205/60 R16	HABILEAD	6 mm
4. Description of Damages				
	THE VEHICLE SUS	STAINED DAMAGES AT THE N/S		
5.	General Information			
	Accident Date	12/10/2021	Inspect Date / Time	25/11/2021 ( 11:45 AM )
	Survey held at	68 Kaki Bukit Ave 6 #03-05		
	Repairer	TRIPLE-T AUTOMOBILE		
5a.	Remarks			
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Report Ref No. CS3/LPC21011726/Gvf3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser

**Automotive Assessor**