

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21011728/EQY3N2**Date:** 04/03/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	SNM21D206601
Claimant Vehicle No :	SKE8785J	Insured Vehicle No :	GBF4860C
Date of Loss:	16/11/2021	Nature of Claim:	TP
		Claim No:	SNM21D206601/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKE8785J	Engine No:	27191031353161
Make & Model:	MERCEDES-BENZ C180, 1.6 Kompressor (A)	Chassis No:	WDD2040452A688068
Reg. Date:	12/04/2012 (Man. Year: 2012)	Odometer:	171843 km
Colour:	Silver		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45R18	Rear Tyre Size:	225/45R18
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,944.10	5,984.60	3,959.50	39.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,290.00	1,340.00	950.00	41.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,234.10	7,324.60	4,909.50	40.13
Approved Total (Overridden) (S\$)		5,850.00		
(S\$)	12,234.10	5,850.00	6,384.10	52.18
+ GST 7.00/7.00% (S\$)	856.39	409.50	446.89	52.18
Nett Amount (S\$)	13,090.49	6,259.50	6,830.99	52.18

INSPECTION

Date of Assignment:	17/11/2021	
Date Inspected:	22/11/2021	Inspected At: Wah Hong Motors & Credit Pte Ltd (HQ) 38 Toh Guan Road East, #01-57, Enterprise Hub Singapore 608581
Estimated Period of Repair:	5.0 days	

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Mar 2022)

Parts: 143 MERCEDES-BENZ C180 1.6 Kompressor (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKE8785J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BOOTLID	Dented	1,849.00 FL	*1,578.00 FL
2	2	*BOOTLID BOTH HINGE LH/RH	Not Necessary	274.00 FL	*- FL
3	1	*BOOTLID LOGO BADGE	Necessary	53.00 FL	*53.00 FL
4	1	*BOOT LID EMBLEM C180	Necessary	94.00 FL	*94.00 FL
5	1	*BOOT LID EMBLEM KOMPRESSOR	Necessary	119.00 FL	*119.00 FL
6	1	*BOOT LID LOCK	Cut	340.00 FL	*282.00 FL
7	1	*TAIL LAMP LH	Cut	705.00 FL	*705.00 FL
8	1	*REAR BUMPER	Crushed	1,436.00 FL	*1,436.00 FL
9	1	*REAR BUMPER CENTER BRACKET	Not Necessary	156.00 FL	*- FL
10	2	*REAR BUMPER TAIL LAMP SIDE LOWER BRACKET LH/RH	Broken	164.00 FL	*164.00 FL
11	2	*REAR BUMPER SIDE RETAINER LH/RH	Broken	130.00 FL	*130.00 FL
12	1	*REAR BUMPER CENTER CHROME	Cut	210.00 FL	*170.00 FL
13	1	*REAR BUMPER SIDE CHROME LH/RH (2 Pcs)	Cut (1 Pc only)	298.00 FL	*130.00 FL
14	1	*REAR BUMPER SIDE LOWER BRACKET LH/RH (2 Pcs)	Broken (1 Pc only)	66.00 FL	*33.00 FL
15	1	*EXHAUST MUFFLER	Not Necessary	1,817.00 FL	*- FL
16	2	*HEADREST LH/RH	Broken	1,858.00 FL	*1,500.00 FL
17	1	*AIRBAG ECU	Not Necessary	1,180.00 FL	*- FL
18	1	*REAR BUMPER CLIPS	Necessary	35.00 FS	*30.00 FS
19	1	*REAR REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
20	1	*REAR CAR PLATE WITH HOLDER	Not Necessary	35.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,019.00	6,624.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,074.90	639.40
Total Parts (\$\$)	9,944.10	5,984.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS;PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS	New	800.00	500.00
2	TO SUPPLY PAINT MATERIALS,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED & REPAIRED	New	800.00	440.00
3	TO REMOVE AND REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREA AND CHECK FOR ALL ELECTRICAL PROPER FUNCTION	New	60.00	40.00
4	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	30.00	30.00
5	TO REMOVE AND REPLACE REAR REVERSE SENSOR	New	100.00	30.00
6	TO REMOVE AND REPLACE EXHAUST MUFFLER	New	200.00	100.00
7	AIRBAG SYSTEM CODING AND RESETTNG	New	300.00	200.00
Gross Labour Cost (\$\$)			2,290.00	1,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >