

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21011735/EYA3Q2**Date:** 01/03/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070063851-01
Claimant Vehicle No :	GBJ4481S	Insured Vehicle No :	YP8465J
Date of Loss:	13/11/2021	Nature of Claim:	TP
		Claim No:	5048481494SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ4481S	Engine No:	1GD8376722
Make & Model:	TOYOTA HIACE, 2.8 D DX (A)	Chassis No:	GDH2012004763
Reg. Date:	25/04/2019 (Man. Year: 2018)	Odometer:	122591 km
Colour:	White		
Engine Capacity:	2754 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Triangle 4 mm	Rear Left Side:	Triangle 4 mm
Front Right Side:	Triangle 4 mm	Rear Right Side:	Triangle 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,680.45	8,647.07	2,033.38	19.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,750.00	1,560.00	1,190.00	43.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,430.45	10,207.07	3,223.38	24.00
Approved Total (Overridden) (S\$)		8,150.00		
(S\$)	13,430.45	8,150.00	5,280.45	39.32
+ GST 7.00/7.00% (S\$)	940.13	570.50	369.63	39.32
Nett Amount (S\$)	14,370.58	8,720.50	5,650.08	39.32
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
+ Other Costs (S\$)		53.50		
Nett Liability (S\$)		9,076.00		

INSPECTION

Date of Assignment:	13/11/2021	
Date Inspected:	17/11/2021 Inspected At:	Efficient Motor & Engineering Works Pte Ltd (HQ) 56 Loyang Way #06-07, Loyang Enterprise Building Singapore 508775
Estimated Period of Repair:	5.0 days	

Adjuster: CHEN TSUE YEE**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	541.20 FL	*541.20 FL
2	1		*FRONT BUMPER SIDE RETAINER RH	Broken	143.40 FL	*143.40 FL
3	1		*HARNESS CASING RH	Broken	93.40 FL	*93.40 FL
4	2		*HEADLAMP ASSY LH/RH	Broken	4,906.20 FL	*4,906.20 FL
5	2		*HEADLAMP BRACKET LH/RH	Not Necessary	59.40 FL	*- FL
6	1		*AIR CLEANER BOX	Broken	801.90 FL	*650.00 FL
7	1		*STEP GARNISH RH	Broken	161.90 FL	*161.90 FL
8	1		*FRT DOOR RH	Dented	1,887.10 FL	*1,887.10 FL
9	2		*FRT DOOR HINGE RH	Not Necessary	220.00 FL	*- FL
10	1		*FRT DOOR WINDOW OUTER MDNG RH	Cut	99.00 FL	*99.00 FL
11	1		*FRT DOOR WEATHERSTRIP RH	Not Necessary	287.50 FL	*- FL
12	1		*FRT DOOR WINDOW REGULATOR RH	Not Necessary	256.30 FL	*- FL
13	1		*FRT DOOR REGULATOR MOTOR RH	Not Necessary	852.10 FL	*- FL
14	1		*FRT PILLAR OUTER RH	Repair	434.20 FL	*- FL
15	1		*SIDE MIRROR ASSY RH	Missing	1,782.90 FL	*1,492.00 FL
16	1		*FRT GRILLE OUTER MDNG TOP	Broken	221.70 FL	*221.70 FL
17	1		*FRT GRILLE OUTER MDNG LOWER	Broken	383.20 FL	*383.20 FL
18	1		*FRT GRILLE INNER	Broken	568.60 FL	*568.60 FL
19	1		*CORNER PANEL (RH)	Dented	268.40 FL	*268.40 FL
20	1		*BRAKE BOOSTER CYLINDER CAP (Missing)	Not Consistent With The Impact	72.20 FL	*- FL
21	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
22	1		*FRONT DOOR STICKER RH	Necessary	50.00 FS	*40.00 FS
23	1		*FRONT GRILLE CLIPS	Necessary	50.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,190.60	11,501.10
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,510.15	2,854.03
Total Parts (\$\$)	10,680.45	8,647.07

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CUT & WELD DAMAGED PANELS FRONT PILLAR OUTER ,STEP PANEL ,FRT FLOOR PANEL & OTHER INNER PANELS ,TO REMOVE & REPLACE DAMAGED PARTS	New	1,000.00	500.00
2	TO CHECK AND RECTIFY LIGHTING & WIRING HARNESS	New	50.00	30.00
3	TO PUTTY ,SPRAY PAINTING FOR FRONT RH ,PORTIONS & AFFECTED AREAS	New	1,000.00	800.00
4	TO TRANSFER COMPONENTS TO NEW DOOR	New	150.00	50.00
5	TO DO ARTWORK COMPANY STICKER	New	350.00	150.00
6	TO APPLY ANTI RUST COAT AND TUFF KOTE AFFECTED AREAS	New	100.00	30.00
7	TO DO WHEEL ALIGNMENT	New	100.00	0.00
Gross Labour Cost (S\$)			2,750.00	1,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >