

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21011738/GPA3Q2**Date:** 07/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900243060-02
Claimant Vehicle No :	SJU2295Z	Insured Vehicle No :	GBF5173X
Date of Loss:	03/11/2021	Nature of Claim:	TP
		Claim No:	9100083322SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJU2295Z	Engine No:	2AZB276845
Make & Model:	TOYOTA HARRIER, 2.4 (A)	Chassis No:	ACU300074372
Reg. Date:	01/08/2007 (Man. Year: 2007)	Odometer:	220138 km
Colour:	Black		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/65 R17	Rear Tyre Size:	225/65 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,466.62	4,382.02	3,084.60	41.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,640.00	1,410.00	2,230.00	61.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,106.62	5,792.02	5,314.60	47.85
Approved Total (Overridden) (S\$)		4,600.00		
(S\$)	11,106.62	4,600.00	6,506.62	58.58
+ GST 7.00/7.00% (S\$)	777.46	322.00	455.46	58.58
Nett Amount (S\$)	11,884.08	4,922.00	6,962.08	58.58
+ Car Rental (5.0 x S\$140.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,629.45		
Global Sum Settlement (S\$)		5,600.00		

INSPECTION

Date of Assignment:	17/11/2021	
Date Inspected:	18/11/2021	Inspected At: Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park Singapore 408934
Estimated Period of Repair:	4.0 days	

Adjuster: XING GUO QIANG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,023.00 FL	*1,023.00 FL
2	2		*REAR BUMPER RETAINER	Deformed	209.00 FL	*137.00 FL
3	1		*REAR BUMPER REFLECTOR LH	Cracked	269.50 FL	*87.10 FL
4	1		*REAR BUMPER REINFORCEMENT	Broken	1,061.50 FL	*329.30 FL
5	1		*REAR BUMPER SPONGE	Cracked	209.00 FL	*111.00 FL
6	1		*TAILGATE	Buckled	1,496.00 FL	*1,496.00 FL
7	1		*TAILGATE RUBBER	Twisted	478.50 FL	*194.10 FL
8	1		*TAILGATE LAMP LH	Broken	247.50 FL	*191.00 FL
9	1		*TAILGATE LOCK	Cut	649.00 FL	*226.00 FL
10	1		*TAILGATE LOCK STRIKER	Not Necessary	159.00 FL	*- FL
11	1		*TAILGATE INNER TRIM BOARD	Broken	628.10 FL	*485.00 FL
12	1		*TAILGATE OUTER CHROME GARNISH	Broken	264.00 FL	*264.00 FL
13	1		*TAILGATE EMBLEM -LOGO	Necessary	118.80 FL	*118.80 FL
14	1		*TAILGATE EMBLEM -LEXUS	Necessary	97.90 FL	*97.90 FL
15	1		*TAILGATE EMBLEM -RX300	Necessary	104.50 FL	*104.50 FL
16	1		*TAILGATE GLASS MOULDING	Necessary	104.50 FL	*104.50 FL
17	1		*WIPER MOTOR	Not Necessary	447.70 FL	*- FL
18	1		*END PANEL	Repair	874.50 FL	*- FL
19	1		*END PANEL TOP GARNISH	Cracked	313.50 FL	*313.50 FL
20	1		*SET REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
21	1		*SET TAILGATE INNER TRIM CLIP	Necessary	50.00 FS	*30.00 FS
22	1		*SET END PANEL INNER TRIM CLIP	Necessary	50.00 FS	*20.00 FS
23	1		*REAR BUMPER TOP RUBBER	Necessary	200.00 FS	*100.00 FS
24	1		*WINDSCREEN SEALANT	Necessary	120.00 FS	*40.00 FS
25	1		*SET REVERSE SENSOR	Damaged	300.00 FS	*200.00 FS
26	1		*SET JOINT SEALANT	Not Necessary	150.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	9,655.50	5,702.70
- List Item Discount on L Items 25.00/25.00% (S\$)	2,188.88	1,320.68
Total Parts (S\$)	7,466.62	4,382.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING AND LIGHTING SYSTEM	New	60.00	30.00
2	R&R TRIMS AND GARNISHES TO FACILITATE REPAIR	New	150.00	60.00
3	R&R REVERSE SENSOR	New	150.00	40.00
4	R&R WINDSCREEN GLASS	New	180.00	120.00
5	TRANSFER TAILGATE MECHANISM TO FACILITATE REPAIR	New	150.00	60.00
6	PANEL BEATING ON AFFECTED AREAS	New	1,400.00	500.00
7	SPRAY PAINTING ON AFFECTED AREAS	New	1,400.00	600.00
8	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	0.00
Gross Labour Cost (\$)			3,640.00	1,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >